

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil &amp; Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator <i>El Paso Natural Gas Co</i>		8. Farm or Lease Name <i>Jordan</i>	
3. Address of Operator <i>Box 289 Farmington</i>		9. Well No. <i>1</i>	
4. Location of Well UNIT LETTER <i>C</i> <i>990</i> FEET FROM THE <i>North</i> LINE AND <i>1450</i> FEET FROM THE <i>West</i> LINE, SECTION <i>23</i> TOWNSHIP <i>29N</i> RANGE <i>11W</i> NMPM.		10. Field and Pool, or Wildcat <i>Antec Fruitland</i>	
15. Elevation (Show whether DF, RT, GR, etc.) <i>5474</i>		12. County <i>SI.</i>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set ~~return~~ B.P. @ approx 1400'  
Spot 10 5x Cement Plug on top of B.P.
2. Perf 650' - Spot 35 5x Cement in Csg.  
Displace 10 5x out
3. Pull up to 150' and fill with cement.



8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Donald C. Adams* TITLE *Manager Production Operations* DATE *3-23-81*

APPROVED BY *Charles Johnson* TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAR 23 1981

CONDITIONS OF APPROVAL, IF ANY: