

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	2
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name WADE
9. Well No. 1
10. Field and Pool, or Wildcat
12. County SAN JUAN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-

2. Name of Operator
BEDFORD, INC. AGENT for ELVIS ROBERTS EST. STATE OF NEW MEXICO

3. Address of Operator
P.O. Box E, FARMINGTON, New Mexico 87401

4. Location of Well
UNIT LETTER B FEET FROM THE LINE AND FEET FROM THE LINE, SECTION 21 TOWNSHIP 29N RANGE 11W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been Plugged & Abandoned as follows:

6-4-79 Move IN, Rig Up, Dick up 1476' 2" + bgy.
Spot 30 sy plug from 1476' to 1250', Pull 30 its + bgy.

6-5-79 Perf 4 holes @ 600', Spot 28 sy Plug @ 600'
Squeezed 14 sy thru Perfs. W.O.C.

6-6-79 Rig up Shooter, tag Plug., Pull to 175', Perf 4 holes @ 175', Fill hole w/ cement 28 sy, Squeeze 14 sy thru. Perfs. W.O.C. Cut off well here
INSTALL P&A MARKER. Rig down, Clean

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry G Bedford TITLE Agent for Operator DATE 6-15-79

Original Signed by A. R. Kendrick
APPROVED BY _____ TITLE _____ DATE JUL 11 1979

CONDITIONS OF APPROVAL, IF ANY:

