

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Melborne Petroleum Corporation Bedford, Inc., Agent for & State of New Mexico	8. Farm or Lease Name R.L. Finch
3. Address of Operator P.O. Box E, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>500</u> FEET FROM THE <u>N</u> LINE AND <u>1800</u> FEET FROM THE <u>E</u> LINE, SECTION <u>22</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> NMPM.	10. Field and Pool, or Wildcat <u>Agter-PC</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned as follows:

- 8-14-78 Move in pump truck, clean out cellar, try to clean out cement in marker. Cut marker off 18" from surface & found cement. Cut hole in plate @ surface.
- 8-15-78 Circulate hole & spot 45 SX from 90' to surface Recover contaminated water & dispose of.
- 8-16-78 Restore surface & clean up. Stencil P & A marker



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Larry A Bedford</u>	TITLE <u>Agent for State</u>	DATE <u>8-31-78</u>
APPROVED BY <u>AR General</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		