

well file

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

May 15, 1964

Mr. James H. Durrett, Jr.
Oil Conservation Commission
Box 2088
Santa Fe, New Mexico

Re: Case No. 3014, Order No.
R-2688, Otto V. Reynolds
#1 Wood, N-14-27N-11W

Dear Mr. Durrett:

I witnessed the plugging operations of subject well on May 13 and 14, 1964.

The following recap of the operation may be used in lieu of Form C-103 normally filed by the operator of a well:

On May 13, 1964 moved in and rigged up. Surface casing found to be 6-5/8". Went into hole with drill pipe. Found what is thought to be the stub of 2-7/8" casing at 150'. Could not make up 2-7/8" pin into stub. Passed stub and went into hole to 240', where a formation bridge was encountered.

May 14, 1964: Cemented through drill pipe at 240' with 32 sacks neat cement. Pulled drill pipe to surface, filled hole with 6 sacks neat cement. Surface marker was not set.

The Wood #1 well was plugged and abandoned under my supervision and in an approved manner.

If further information is desired, please contact me.

Yours very truly

*A. R. Kendrick
Engineer, District #3*

ARK:ks

cc: *Mr. Carl Kay (Contractor)
506 North Orchard
Farmington, N.M.*

*Mr. Otto Reynolds
630 Grant Way
Oxnard, California*

*Mr. James E. Perry
The Continental Insurance Co.
212 Second Street NW
Albuquerque, New Mexico*