

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Barnhart
8. Well No. 1
9. Pool name or Wildcat Fulcher Kutz Pic Cliffs

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
Southland Royalty Company

3. Address of Operator
PO Box 4289, Farmington, NM 87499

4. Well Location
Unit Letter L : 2310 Feet From The South Line and 990 Feet From The West Line
Section 17 Township 29N Range 7W 11 NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-31-88 MOL&RU. NDWH. Cut csg nut. NU WH. Test BOP. Unseat Baker D-A packer & TOOH w/pkr & 2 3/8" tbg. LD pkr. TIH w/tbg. String to 188.98'. Est. Flow rate w/10 bbls. 9# mud. Spot 55 sx plug & TOOH w/33 jts. tbg. Displaced tbg left in hole w/6 bbl 9# mud. Unable to reverse circ due to csg. condition. WOC. SDFN.

11-01-88 TIH, tag cmt. plug @ 1664'. Pull 1' off plug, spot 30 sx. Cl B neat cmt on top of plug. Mr. Gholson of NMOCD gave permission not to WOC. Pulled tbg to 540.58'. TIH, shot 4 holes @ 577.50'. Run tbg to 635.44'. Pump 265 sx per Mr. Gholson. WOC. Tag plug @ 160'. Pull off to 158'. Cmt to surface w/115 sx Class "B" neat cmt. TOOH w/tbg. RD BOP. Cut off csg & install dry hole marker w/30 sx. Cl B neat cmt. Released rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charles Gholson TITLE Regulatory Affairs DATE 1-9-89
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)
Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

JAN 16 1989

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: