

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-63
2. NAME OF OPERATOR Humble Oil & Refining Co.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo
3. ADDRESS OF OPERATOR P. O. Box 120 Denver, Colorado 80201		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface NW 1/4 SW 1/4 (1830' PSL & 660' PVL) Sec. 17-29N-15W		8. FARM OR LEASE NAME Navajo Tract 2A
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5394' GR.	9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT South Waterflow
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17-29N-15W
		12. COUNTY OR PARISH San Juan
		13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 4302' - PWD 4274'.

Well plugged and abandoned as follows:

25 sacks cement across perforations 4213-44' and squeezed slightly.
Cut 1/2" casing at 3097' and pulled.
100' plug (25 sacks) 50' below and 50' above casing cut at 3097'.
100' plug (25 sacks) 850'-950'.
15' surface plug with regulation marker. Intervals between plugs filled with mud. Plugging complete 12-13-66.
Location cleaned, pits filled and ready for inspection.



18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by: Roger S. Frazier TITLE Dist. Oper. Supt. DATE

(This space for Federal or State office use)

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: