Form 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES BUBMIT IN TRIE (Other instruction verse side)

PLICATE*	Budget Bureay No. 1004–6. S Expires August 31, 1985
	Expires August 31, 1985 5. That an all the second s

Expi	res A	lugy's	t 31,	1985
Ind a	H ^s 'A	177 61	tè	BERIA

Expires August 31, 1985	
Indian Alyotteu seeia.	١,
"Indian Avioced	
#14-20-603-5036	

BUREAU OF LAND MANAGEMENT	#14-20-603-5036
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	Navajo
Depleted Reference 14-20-603-5036	7. UNIT AGREEMENT NAME
WELL X WELL OTHER 3162.3-4 (016)	
NAME OF OPERATOR	8. FARM OR LEASE NAME
Texas Eastern Developments, Inc.	9. WBLL NO.
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	# 23 Shinrock /6/
P. O. Box 2521 Houston, TX 77252-2521 NECLTVL.	# 23 Shiprock 16L
See also apace 17 below.) At surface APR 1 0 1987	Shiprock-Gallup
	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
1911 ' FSL & 1/3 ' FWL BUREAU OF LAND MANAGEMENT	500 16 T20N D19W
FARMINGTON RESOURCE AREA 14. PERMIT NO. 15 ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec. 16, T29N, R18W
5/84.47 GR.	San Juan NM
Check Appropriate Box To Indicate Nature of Notice, Report, or C	
NOTICE OF INTENTION TO:	UENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING OTHER PLANS (Other)	ABANDONMENT*
(Norm: Report result	s of multiple completion on Well eletion Report and Log form.
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates proposed work. If well is directionally drilled, give subsurface locations and measured and true vertice. 	
nent to this work.) * Well Data	
Well Data Spud <u>3/30/61 TD /36 H</u> ole Size <u>63/4</u> Casing <u>5½</u> @ 109 'c	mt'd w/ 6.0 sx.
Casing Recovered: Size — Amount of ft.	
casting Recovered.	
ribude ing interval.	
Method of Plugging: Halliburton Pump Type Cement: Portland w/8% Bentonite, slurry wt. 13.3 ppg, slurr	v vol. 1.82 cu ft/sx.
Remove rods, pump and tubing.	10'
1st stage cement: Squeeze 7.5 cu ft, set plug 122 ' to s	urfac e w/ /6.8 cu ft.
Ton compart at /a !	Million Co.
2nd stage cement: set plug 60 ' to surface w/ 6.0 cu ft	depend of E 1 V E
<u>Dates</u>	U D
Notice of intent to plug approved: JAN 29, 1987	APR 2 0 1987
Well plugged: MARCH 13, 1987	OIL CON. DIV
Land Restored: MARCH 19,1987	
Marker set: March 24, 1987 Approved to to plugging to the Marker set: March 24, 1987 Liability under bond to receive	
Land seeded: surface restoration is complete	ਚੌਕ <u>,</u>
	ADDOMINO
18. I hereby certify that the foregoing is true and correct	
NOTE H. N. Line do TITLE	DATE
M. N. Hinds Drilling Superintendent	
(This space for Federal or State office use)	APR-15 1987
APPROVED BY TITLE	DATE JENT
CONDITIONS OF APPROVAL, IF ANY:	James Jeden
	FARMANGTON RESOURCE ACTES
*See Instructions on Reverse Side	* Let Have \$00 (Do a startbooks some principle)