

N. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well	7. Unit Agreement Name
2. Name of Operator Exxon Company, U.S.A.	8. Form or Lease Name NW Cha Cha PM Project (Formerly Brimhall #1)
3. Address of Operator P. O. Box 120, Denver, Colorado 80201	9. Well No. 23-17
4. Location of Well UNIT LETTER <u>K</u> <u>2580</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>29N</u> RANGE <u>14W</u> NMPM.	10. Field and Pool, or Wildcat Cha Cha Gallup
15. Elevation (Show whether DF, RT, GP, etc.) 5166' KB	12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-18-72: Tubing stuck in packer at 4568'. Mixed 12 sx cement and squeezed below packer. WOC.
- 1-19-72: Cement plug did not hold. Resqueezed w/10 sx cement. WOC.
- 1-20-72: Shot tubing off at 4150'. Spotted 10 sx cement plug 3850-3750'.
- 1-21-72: Shot 4½" csg. at 3080'. Pulled csg. Spotted 40 sx cement plug at 800', 40 sx cement plug 500-400', 40 sx cement plug 217-177'.
- 1-22-72: Set regulation dry hole marker in top of surface casing w/10 sx cement plug from 30-0'. Intervals between plugs filled with mixed mud.
- 2-7-72: Location cleaned, ready for inspection.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Dist. Secy. DATE 1-22-72

APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE FEB 20 1972

CONDITIONS OF APPROVAL, IF ANY: