		, !	•	•
- ingues		•	,	Form C-103
O. OF COPIES RECEIVED		:		Supersedes Old C-102 and C-103
DISTRIBUTION	NEW MEXICO OIL C	ONSERVATION C	OMMISSION: P.P. 200	Effective 1-1-65
NTA FE	<b></b>			
LE	•	·	≫ <u>12.3</u>	Sp Indicate Type of Lease
s.g.s.	•			State Fee. X
PERATOR	•		1 2 1086	5. State Oil & Gas Lease No.
ERATOR			La San	á
SUNDRY	NOTICES AND REPORTS	ON WELLS	Die	
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR P FOR PERMIT -" (FORM C-101) FO	LUG BACK TO A DIFFE R BUCH PROPOSALS.)	neid Waltham.	
		-		7. Unit Agreement Name
WELL SAS WELL W	OTHER-			
ame of Operator				8. Farm or Lease Name
Beta Developmen	t Company			Fogelson 10
ddress of Operator			•	9. Well No.
238 Petroleum P	laza, Farmingtor	n, NM 8740		1510 1/
ocation of Well				10. Field and Pool, or Wildcat
E 18	50 FEET FROM THE NO	orth LINE AND	990 PEET PRO	Basin Dakota
UNIT LETTER				
THE West LINE, SECTION_	10 TOWNSHIP 25	9N RANGE -	11W HMP	<u> </u>
THE CINE, SECTION				
IIIIIIIIIIIIII	15. Elevation (Show wh		ise.)	12. County
	5	723' G.L.		San Juan
Check App	propriate Box To Indica	te Nature of No	otice, Report or C	ther Data
NOTICE OF INTE		1		NT REPORT OF:
NOTICE OF INVE		:		
	PLUG AND ABANDON	REMEDIAL WO	ak 🔲 .	ALTERING CASING
FORM REMEDIAL WORK		—	ILLING OPNS.	PLUG AND ABANDONMENT
APORARILY ABANDON	CHANGE PLANS	CASING TEST	AND CEMENT JOB	
L OR ALTER CASING		OTHER	Repair well	^
		$\Box$		•
OTHER			· ·	
Describe Proposed or Completed Operat	ions (Clearly state all pertinen	t details, and give t	pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1 105.	ŧ .			
4-23-86 Move	in work over r	ig and rig	up well hea	ad, set B.O.P. load tub
4-23-86 MOVE	lanking plug an	d tubing t	φ 2000 PSI c	o.k. release on & off
w/water, test L	and halo w/wate	r cir ho	le clean. P.	O.H. pick up Bakers
tool @ 634/ , 1	oad noie w/wace	top hole	0 3402 and h	oottom hole @ 4362',
full bore packe	r, T.I.H. Iound	/tubing	onen ended t	-0 4363' Spot cement
P.O.H. lay down	packer, T.I.H.	w/ cubing	open ended (	to 4363'. Spot cement
from 4362-3092	pick tubing up	21 - 1 - 2 - 2	and reverse	out & bbl. cement,
spot cement dow	n tubing to 309	2. close p	ack side and	d squeeze 500 sx class
"B" cement + 8%	; gel + 2% ca. c	1. displac	e tubing + 3	bbl's over, shut down
hr. W.O.C. pr	essure was up t	o 1200# do	wn to /00# a	at end of ½ hr. no flow
hack POH cl	lose B.O.P. and	put 800# 0	n cement, W.	.O.C. T.I.H. W/4-3/4"
hit tag cement	- @ 3274' drill	solid ceme	nt to 4375'	(2-test) held o.k.
test after all	cement drilled	to 1500# o	.k. cir. hol	le clean, P.O.H.
tubing and bit.	. pick up on & o	ff tool, T	.I.H. to 634	44' found 3' fill,
dimp nit and cl	lean. mix pit of	KCL water	, displace h	hole and wash top or
nacker off spo	ot 5 dals, soap	in bottom	ち of csg. ai	nd latch up on & oii
Lool after swah	shina fluid down	to 3000'	release pack	ker, P.O.H. lay down
· macker and all	tools trip in	hole $w/225$	its. 2-3/8	" EUE tubing w/bar
packer and arr	om and land donu	t. remove	B.O.P. set	well head, released
COLIAT ON DOCTO	7.00 D M Labut	woll in n	o-market).	
rig 1-26-86 at hereby certify that the information above	ve is true and complete to the	est of my knowledg	and belief.	
	ــــــــــــــــــــــــــــــــــــــ		!	
Cloke B 1/och	ALS V TITLE	sst Superi	ntendent	
10				
	✓	SUPERVIS	OR DISTRICT # 3	MAV 1 9 100£
Original Signed by FRANK	T. CHAVE <b>Z</b>			MAY 12 1986