Sumit 3 Copies to Appropriate District Office

State of New Mexico

Energy, Minerals and Natural Resources Department

DISTRICT P.O. BOX 1980, Hobbs, NM 88240

DISTRICT II P.o. Box DD, Artesia, NM 88210

OIL CONSERVATION DIVISION

2040 Pacheco St. Santa Fe, NM 87505

WELL API NO. 30-045-08640 INDICATE TYPE OF LEASE STATE _ FEE X

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. STATE OIL & GAS LEASE NO.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFRENCE BOOK OF THE PROPOSALS TO DRILL OR TO DEFRENCE BOOK OF THE PROPOSALS TO THE PROP	7. LEASE NAME OR UNIT AGREEMENT NAME FIFIELD 5
1. TYPE OF WELL: OIL WELL GAS WELL OTHER	
2 NAME OF OPERATOR	8. WELL NO.
	#1
3. ADDRESS OF OPERATOR 10 DESTA DR., SUITE 100W, MIDLAND, TX 79705-4500 (915) 686-5424	9. POOL NAME OR WILDCAT BASIN DAKOTA
10 DESTA DR., SUITE 100W, MIDLAND, TX 79705-4500 (915) 686-5424 4. WELL LOCATION	BASIN DAROTA
Unit Letter \underline{N} : $\underline{790}$ Feet From The \underline{SOUTH} Line and $\underline{1450}$ Feet From The \underline{WEST} Line	e
Section <u>05</u> Township <u>29N</u> Range <u>11W</u> NMPM <u>SAN JUAN</u> County	
10. ELEVATION (Show whether DF, RKB, RT, Gr, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or NOTICE OF INTENTION TO: SUE	Other Data SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT	JOBS 🗍
OTHER: CASING TEST	7/TBG CHANGEOUT
12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-5-97 MIRU. STING OUT OF MODEL D PKR, RECOVERED 6340' OF TBG, RIH W/ MILL AND 198 JTS OF 2-3/8" AND TAG PKR AT 6336' MILL ON PKR, POOH W/ TOOLS, PKR NOT ATTACHED, TIH W/ 209 JTS 2-3/8" AND TAG FILL AT 6624', POOH W/ TBG AND RIH W/ RBP AND PKR TO 3382' AND FOUND TIGHT SPOT, POOH W/ TOOLS, TIH W/ 3-7/8" BIT AND SCRAPPER TO 6500' - OK, POOH W/ TOOLS, RIH W/ RBP AND PKR AND SET RBP AT 6366', PU 31' AND SET PKR, TEST RBP TO 500# - OK, TEST CSG ABOVE PKR,	
PUMP INTO 2.5 BPM 500#, REL PKR AND START TESTING 4-1/2" CSG TO ISOLATE LEAK, BAD PIPE FROM 1100' - 4869', TOOH W/ PKR, RIH W/ RET HEAD AND 201 JTS 2-3/8" TBG, CIRC HOLE, RU TO SWAB FLUID OFF RBP, SWAB FLUID, RIH LATCH RBP AND TOOH, RIH W/ 2-3/8" SN, 31 JTS 2-3/8" TBG, HBTON R-4 PKR AND 175 JTS 2-3/8" J-55 8RD 4.7# TBG AND LAND AT 6480', R-4 PKR AT 5500', PERFS FROM 6402' - 6580', SWAB AND UNPLUG TBG, DO PRESSURE BUILDUP, REL R4-PKR AND POOH RIH W/ 4-1/2" RBP AND PKR AND ISOLATE CSG HOLES AT 4769', 2.5 BPM AT 300#, 4060' 2 BPM AT 300#, 1666' HOLDS 200# BLEEDS OFF FROM 500#, 1100' HOLE CIRC TO BH, POOH W/ PKR, LEFT RBP AT 4000', RIH AND RESET PKR AT 5400', RIH AND SET R-4 PKR AT 3873', SQEEZE HOLES FROM 4060' - 4769' W/ 100 SXS CLASS B W/ 2% CACL, DISPLACE W/ 16 BBLS, HESITATE SQEEZE 0.9 BBL AT 750#, RD BJ, REL PKR, PU TO 1600' CIRC CLEAN, POOH W/ PKR, TIH W/ R-4 PKR AND SET AT 1900' TEST LOWER SOCEZE TO 500# - OK, REL PKR, PU AND SET AT 890', SQEEZE HOLES FROM 1100' - 1666'. PUT 500# ON CSG ABOVE PKR, PUMP 10 BBLS DYE CUT FLUID, LEAD IN W/ 190 SXS 65/35/6% GEL W/ 1/4#/SX CELLO SEAL, TAIL IN W/ 100 SXS CLASS B W/ .5# FL-62 (FLUID LOSS), DISPLACE W/ 5.4 BBLS HESITATE SQEEZE TO 500#, REL PKR POOH, PU 3-7/8" BIT AND 4 3-1/8" DC, TIH AND TAG CMT AT 1040', PO TO 1325', CIRC HOLE CLEAN, DO CMT 1325' TO 2300', CIRC CLEAN, TEST TO 650# - OK (TOP SQEEZE IS GOOD), TIH TO TO.C. AT 3900' AND DO CMT TO 5473'. TEST TO 600# - LEAK OFF IN 5 MIN CIRC HOLE CLEAN, TOOH W/ TOOLS, BOTTOM SQEEZE WILL BE REDONE, TIH W/ TBG TO 4800', RU TO SPOT BALANCED PLUG ACROSS 4060' - 4770', REV CIRC CLEAN, SPOT 40 SXS CLASS B W/ 3% FR AND 35 SXS CLASS B W/ 3% FR AND 2% CACL, WASH P&L., PU TO 3580' REV CIRC CLEAN, W/ 32 BBLS, SQEEZE TO 1000#, TOTAL 2 BBLS DISPLACED, TEST CSG W/ TBG IN HOLE 500# - OK, TOOH W/ TBG, TIH W/ BIT. TAG CMT 4055' TO 4845', CIRC CLEAN, TEST TO 500#, DID NOT BLEED TO 0#, TOOH W/ TOOLS, TIH, REL R8P AND TOOH W/ SAME, TIH W/ 2-3/8" SN AND 206 JTS J-55 8RD 4.7# EUE TBG AND LAND AT 6478', RU TO SWAB, KICKED OFF WELL. 3-4-97	
C 18th Color of	20 INO - 2 44 27
TYPE OR PRINT NAME DEBRA BEMENDERFER	CO INC. DATE 3-11-97 TELEPHONE NO
APPROVED BY CONDITIONS OF APPROVAL, IF ANY. CONDITIONS OF APPROVAL, IF ANY.	MAR 1 4 1997