

S- 3-23-61

F. Loc. 1750/S; 1820/E

Elev. 5510 GL

Spd. 3-24-61

Comp. 4-9-61

TD 5925

PB 5748

Casing S. 2 3/8 @ 327 W. 152 Sx. Int. @ W. Sx. Pr. 7/2 @ 5934 W. 656 Sx. T. 2 3/8 @ 5748

Csg. Perf.

Prod. Stim.

EPG

I.P. 1985 MCF/D After 3 Hrs. SICP 1691 PSI After 7 Days GOR 6-25-79 1st Del. 10-17-61

TOPS		NITD	Well Log	TEST DATA						Ref. No.
			Plat	Schd.	PC	Q	PW	PD	D	
Kirtland	70	C-102	✓	13/4/61	1344	179	452	672	158	#6676
Fruitland		C-103	✓	4/2/62	1411	185	441	726	157	
Pictured Cliffs	146	C-104	✓	4/2/63	1252	154	438	626	142	
Cliff House		9-23-79 12-1-61	✓	11/64	1180	59	473	590	50	X
Menefee	107	Ditr 1-4-62	✓	5/25/65	965	19	456	482	19	X M
Point Lookout	3612	Datr 11	✓	6/25/79	337	5	276	169	9	#5708
Mancos	3415	9-18-79	Remarks	disconnected	6/3/76					6777
Gallup		NIT repair - 11-6-78								
Dakota 16	5775	8/1/90 NIT repair FRZ. Coater 100% D.K.								
Morrison		8/1/90 Re-completed " "								
Entrada		20NC AVE. 15-1-90								
NAME CHANGED FROM SUNRAY MID-CONTINENT OIL COMPANY			E 316.65							
TO SUNRAY OX OIL COMPANY EFFECTIVE MAY 1, 1962.										

Sh. del. -190

P

o

Basin Dak

Co SJ c 2

T 29N

R 14W

U J

O per.

Dugan Prod. Corp.

Com

[No.]

June | July | Aug. | Sept. | Oct. | Nov. | Dec.