

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NM-038377
7. Unit Agreement Name
8. Farm or Lease Name Fifield Federal
9. Well No. 1
10. Field and Pool, or Wildcat Basin Dakota
12. County San Juan

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-

2. Name of Operator
Beta Development Company

3. Address of Operator
238 Petroleum Plaza, Farmington, NM 87401

4. Location of Well
UNIT LETTER G 1620 FEET FROM THE North LINE AND 1475 FEET FROM
THE East LINE, SECTION 5 TOWNSHIP 29N RANGE 11W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
5786' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P & A:
Pump 25 sacks reg. cement thru cement retainer @ 6309'.
Pump 20 sacks reg. cement @ base of Mesa Verde section across D. V. tool @ 4768'.
Pump 20 sacks reg. cement @ top of Mesa Verde section @ 3703'.
Pump 20 sacks reg. cement across D. V. tool at base of Pictured Cliffs @ 2199'.
Shoot into and pull all free pipe above cement of D. V. Tool @ 2199'.
Spot 25 sacks 50' in csg. stub + 50' out.
Spot 35 sacks at base of Ojo Alamo @ 770 (670-770) 8" open hole.
Spot 35 sacks 50' in + 50' out of 8-5/8" surface pipe set @ 298', (348-248)
Pump 10 sacks in top of 8-5/8" surface pipe, install dry hole marker.

RECEIVED

JUN 18 1986

OIL CON. DIV.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **DIST. 3**

SIGNED D. E. Baxter TITLE Superintendent DATE June 13, 1986

ORIGINAL SIGNED BY ERNIE BUSCH

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE JUN 20 1986

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY: o.c.d. to witness plugging