

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Pruitt
9. Well No. 1
10. Field and Pool, or Wildcat Basin Dakota
12. County San Juan

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Pioneer Production Corp. 3. Address of Operator P. O. Box 234, Farmington, N. M. 87401 4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1170</u> FEET FROM THE <u>west</u> LINE, SECTION <u>4</u> TOWNSHIP <u>29N</u> RANGE <u>13W</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 5417'	7. Unit Agreement Name 8. Farm or Lease Name Pruitt 9. Well No. 1 10. Field and Pool, or Wildcat Basin Dakota 12. County San Juan
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged for abandonment in the following manner:

1. Spotted 25 sx. cement plug 5700' - 6000'.
2. Shot 4 1/2" csg. off @ 1385'.
3. Spotted 45 sx. cement plug 1385' - 1235'.
4. Pulled 4 1/2" csg.
5. Spotted 35 sx. cement plug 350' - 215' - base of surface csg.
6. Installed dry hole marker and cleaned location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jim L. Jacobs TITLE Agent DATE 10/20/71

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DIST. NO. 8 DATE 11-10-71
CONDITIONS OF APPROVAL, IF ANY: