DIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

January 4, 1962

Mr. Carl Elgin Ridgway, Colorado

Dear Siri

We received your letter of December 27, 1901 requesting release of your plugging bond on a well which was drilled as the Mobert.

H. Long #1 Bigin in the NW NW Section 3-29N-11W.

The Well Record form which was filed does indicate that the well was properly plugged! however a report of plugging was not filed on Form C-103. We are, therefore, mailing you a supply of this form along with a copy of the Well Record form in order that you may review the information in the event you no longer have the plugging information. Will you please fill out Form C-103 indicating exactly where cerent plugs were set, what was used to fill between the plugs and whether or not the location was levelled. Upon receipt of this form in triplicate we will cancel your plugg as bond.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA : ke

cc: Ar. Ralph Trujillo OCC. Santa Fe, N.M.

Pontleren:

In Decadeber 1956 I drilled a well on least ρ 3 steps -79-BL in 3-29-11 San Juan Dourty uncorone large of Republican.

If it call was plu ged and as for as it come as cabinizability to your A pt. No date I have not receive a melease on my bond.

inular on the ase obenk into this as son as it of the one base the or propal date of the plug-ring.

Terytiff Dy yours,
Carl Din
Ridges, Colo.

