



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Section No. 95-225.4
Approval expires 12-31-52.

Lead Office Santa Fe
Lease No. 978372
Unit S/2 Section 21

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASINGS
NOTICE OF INTENTION TO <u>REPAIR</u> REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 23, 1962

Flores
Well No. 40 is located 1630 ft. from N line and 1825 ft. from E line of sec. 21

NE/4 Sec. 21 34-N 8-W 102W
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Alamosa - Manzanita San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3819 ft. D.F.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing jobs, and all other important proposed work.)

Pump 134 and down braden head. If Braden head still has pressure, pump cement down braden head, displacing cement in surface casing with water.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Balke-Taylor Oil Corporation

Address P. O. Drawer 1198

Farmington, New Mexico

Original signed by
By G. T. HIGGINBOTHAM
Title G. T. Higginbotham
District Superintendent