

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
APR 17 1995
OIL & GAS DIV.
DIST. 2

RECEIVED
BLM

Sundry Notices and Reports

95 APR 13 PM 2:42

070 FARMINGTON, NM

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
990'FNL, 990'FEL, Sec.14, T-30-N, R-8-W, NMPM

- 5. Lease Number
NM-012708
- 6. If Indian, All. or Tribe Name
- 7. Unit Agreement Name
- 8. Well Name & Number
Howell E #2
- 9. API Well No.
30-045-09519
- 10. Field and Pool
Blanco Mesaverde
- 11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

- 3-30-95 MIRU. SDON.
- 3-31-95 ND WH. NU BOP. TOO H w/16 jts tbg. Tbg parted. TIH w/fishing tools. Tbg stuck @ 3836'. TOO H. TIH w/1 13/16" cutter. Could not get past fish @ 548'. POOH. TIH w/1 1/16" gauge ring to 700'. POOH. TIH w/1 11/16" cutter to 2036'. POOH. SD for weekend.
- 4-3-95 TIH to 3706'. Shot tbg @ 3675'. Unable to free tbg. Tbg parted @ 3700'. POOH w/119 jts tbg. TIH w/7" guide ring to 3670'. POOH. TIH w/7" cmt retainer, set @ 3609'. Load hole w/147 bbl wtr. PT csg to 500 psi, OK. Establish injection. Plug #1: pump 20 sx Class "B" cmt on cmt retainer @ 3502-3609'. TOO H to 2769'. WOC. SDON.
- 4-4-95 Establish circ w/4 bbl wtr. Plug #2: pump 99 sx Class "B" cmt inside csg @ 2255-2769'. TOO H to 1773'. Establish circ. Plug #3: pump 67 sx Class "B" cmt @ 1773-1425'. TOO H. TIH, perf 2 sqz holes @ 333'. Establish circ down csg & out bradenhead w/6 bbl wtr. Plug #4: pump 127 sx Class "B" cmt through 7" csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. SDON.
- 4-5-95 ND BOP. Cut off WH. Fill 7" csg w/18 sx cmt. Install dry hole marker w/51 sx Class "B" cmt. RD. Well plugged and abandoned 4-5-95.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 4/13/95

(This space for Federal or State Office use)
APPROVED BY _____ Title _____ Date _____
CONDITION OF APPROVAL, if any:

APPROVED

APR 14 1995

NMOCD

[Signature]
DISTRICT MANAGER