



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS  
GOVERNOR

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

September 9, 1987

Mr. Bennie Brown  
Union Texas Petroleum Corp.  
375 US Highway 64  
Farmington, NM 87401

Re: Julander #1 J-31-29N-11W

Dear Bennie:

The regularly scheduled bradenhead test on the referenced well indicates a casing failure.

In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson  
Deputy Oil & Gas Inspector

CG/dj

xc: Well File



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

BRADENHEAD TEST REPORT  
(Submit 2 copies to above address)

Date of Test 8-18-81 Operator Union Texas Petroleum Corp.

Lease Name Julander Well No. 1 Location U J Sec 31 Twp 29N Range 11W

Pressure (Shut-in or ~~Flowing~~) Dwt Tubing 510 Intermediate      Casing 160 Bradenhead 160

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:	
	INTERMEDIATE	CASING
5 Min.		<u>100</u>
10 Min.		<u>78</u>
15 Min.		<u>70</u>
20 Min.		
25 Min.		
30 Min.		

BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
Steady Flow <u>    </u>	
Surges <u>light</u>	
Down to Nothing <u>    </u>	
Nothing <u>    </u>	
Gas <u>✓</u>	
Gas & Water <u>    </u>	
Water <u>    </u>	

If Bradenhead flowed water check description below:

Clear       
Fresh       
Salty       
Sulfur       
Black     

Remarks: Sulfur Smell Gas bubbling  
This water but no water  
came to surface

By Bennie Brown  
Production Foreman  
(Position)