(SUBMIT IN TRIPLICATE)

Senta Pe Lease No. SF 078931-B UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO BETT		- 11			
NOTICE OF INTENTION TO CHANGE		SUB	EQUENT REPORT OF WAT	TER SHITT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS.		Subs	SUBSEQUENT REPORT OF SHOOTING OR ASSESSED.		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO RE-DRILL	OR REPAIR WELL	SUBS	EQUENT REPORT OF RE-E	DULING OR THE	
NOTICE OF INTENTION TO SHOOT OF	R ACIDIZE	SUBS	EQUENT REPORT OF ABAI	MILLING OR REPAIR	
NOTICE OF INTENTION TO PULL OR	ALTER CASING	SUPP	EMENTARY WELL HISTOI	IDONMENT	
NOTICE OF INTENTION TO ABANDON	WELL				
(INDICA	TE ABOVE BY CHECK MARK	K NATURE OF	REPORT, NOTICE, OR OTH	ED DATA)	
					_
UBA Glenn H. Callo	•			Ostober 20	19 61
Vell No. 20	1000	(ND)			
Vell No. 20 is locat	ed 1500 ft. from		and 1980 ft. fr	rom E line of s	ec. 33
NE/4 Sec. 33 (14 Sec. and Sec. No.)	zy n	13 M	W.M.P.)		
	(Twp.)	(Range)	(Meridian)		
Totah (Field)	San J	BER	,	Mant Manday	
, ,	(County or	r Subdivision)		(State or Territory)	
ate names of and expected depths to o	DETAII bjective sands; show sizes ing points, and all ot	LS OF Was, weights, and her important	ORK d lengths of proposed car t proposed work)		
ate names of and expected depths to one and comented surface by Joints (123') 8-5, 0 sacks coment, 25 Cac 8 hours. Pressure 11d o.k.	DETAII bjective sands; show sizes ing points, and all oti casing as follows, 3-55,	LS OF Was, weights, an her important liews:	ORK d lengths of proposed can t proposed work) asing set at 1 t to surface. N	Plus down 11 DV 2 1961 CON. COM.	ited with
n and comented surface n and comented surface n 4 joints (123') 8-5, 0 sacks coment, 25 Cac C 8 hours. Pressure 1 ld o.k.	DETAII bjective sands; show sizes ing points, and all ot casing as for (8", 24", 3-55, 21g. Circulate casted casing t	LS OF Was, weights, an her important licve; smls end comme	ORK d lengths of proposed can t proposed work) asing set at 1 t to surface. N	Plug down 11 Plug down 11 OV 2 1961 CON. COM. DIST. 3	ited with -15-61.
names of and expected depths to one and comented surface in 4 joints (123') 8-5, 0 sacks coment. 24 Cas	DETAII bjective sands; show sizes ing points, and all ot casing as for 3", 24, 3-55, i.g. Circulate casing t	LS OF Was, weights, an her important licws; suls end comments of	ORK d lengths of proposed car t proposed work) asing set at 1 t to surface. Cands for 30	Plug down 11 Plug down 11 OV 2 1961 CON. COM. DIST. 3	ited with 1-15-61. Sure
n and comented surface 1 and comented surface 1 4 joints (123') 8-5, 0 sacks coment, 25 Cac C 8 hours. Pressure 1 1d o.k.	DETAII bjective sands; show sizes ing points, and all oil casing as foll 8", 24", J-55; lg. Circulate casing to streceive approval in writing ton, acting by	LS OF Was, weights, an her important licws; suls end comments of	ORK d lengths of proposed can t proposed work) asing set at t to surface. Ounds for 30	Plug down 11 Plug down 11 OV 2 1961 CON. COM. DIST. 3	ited with -15-61.

.