

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

<p>1. Type of Well Other</p> <p>2. Name of Operator Norman Gilbreath</p> <p>3. Address & Phone No. of Operator P.O. Box 208, Aztec, NM 87410</p> <p>Location of Well, Footage, Sec., T, R, M 910' FNL and 1550' FWL, Sec. 7, T-29-N, R-12-W,</p>	<p>5. Lease Number NM-02989</p> <p>6. If Indian, All. or Tribe Name</p> <p>7. Unit Agreement Name</p> <p>8. Well Name & Number Moonlight Mesa #1</p> <p>9. API Well No. 30-045-20206</p> <p>10. Field and Pool West Kutz FtC</p> <p>11. County & State San Juan County, NM</p>
---	--

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

This well was plugged and abandoned on November 15, 2001 per following:

- 11-14 MO, RU. Safety Meeting. Layout relief line to pit. Blow down 110# tubing, casing and 80# bradenhead. ND wellhead. NU BOP, test. LD 53 joints 1" pipe, total 1113'. TIH with 1-1/4" workstring. Tag fill on existing CIBP at 1285'. J. Morris with BLM, approved procedure change. Plug #1 with 12 sxs cement inside casing from 1285' to 849' to fill Fruitland perforations and to cover top. SI & WOC.
- 11-15 Safety Meeting. Blow down 60# bradenhead pressure. TIH and tag cement at 1084', cement fell back. Pressure test casing to 500# for 10 min, held OK. Plug #1b with 4 sxs cement inside casing from 1084' to 939' to cover Fruitland top. TOH and LD tubing. Perforate 2 bi-wire squeeze holes at 310'. Establish circulation out bradenhead with 7 bbls water. Plug #2 with 52 sxs pumped cement down the 2-7/8" casing from 310' to surface, circulate good cement out bradenhead. Shut in well. Cut off wellhead. Found cement at surface in 5-1/2" casing and down 12" in 2-7/8" casing. Mix 12 sxs cement, top off casing and install P&A marker. RD and MOL. No BLM representative was on location.

14. I hereby certify that the foregoing is true and correct.

Signed Norman Gilbreath Title Operator Date 12/5/01
Norman Gilbreath President

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____
CONDITION OF APPROVAL, if any: **FOR RECORD**

44000

JAN 24 2002
RECORDING OFFICE
Sm