

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-10010

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N22210

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

North Hoback 12

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Slickrock - Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

N14PM

12. COUNTY OR PARISH

San Juan

13. STATE
N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR

Walter Duncan

3. ADDRESS OF OPERATOR

P.O. Box 234, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990' FS1 1980' PSE1

Section 12 T29N R17W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, or, etc.)

5039 GG

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon this hole in
the following manner:

1. Spot plug from 747 TD to 660'
to cover Dakota Fm.
2. Spot plug over Gallup Fm from 260' to 190'
3. Spot 50' plug at surface
4. Cut surface pipe off below plug
depth & abandon well.

Verbal instructions obtained 7-19-68

18. I hereby certify that the foregoing is true and correct

SIGNED

J. S. Jarama

TITLE

AgentDATE 3-10-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

DATE

MAR 12 1973

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

