submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| Sundry Notices and Reports on Wells 7:57 | - | | |
|--|--|-------------------------------------|--|
| CONTRACTOR OF | 5. | Lease Number NM-03561 | |
| 1. Type of Well GAS | 6. | | |
| 2. Name of Operator APR 2001 | 7. | Unit Agreement Name | |
| BURLINGTON OF PROCEIVED RESOURCES OIL & GAS COMPANY OF OR CON DIV | | | |
| 3. Address & Phone No. of Operator | | Well Name & Number Grenier B #6 | |
| PO Box 4289, Farmington, NM 87499 (505) 32 700 | | API Well No. 3004520717 | |
| 4. Location of Well, Footage, Sec., T, R, M 1650' FSL, 1650' FWL, Sec. 05, T-29-N, R-10-W, NMPM | | Field and Pool Aztec PC | |
| | 11. | County and State San Juan Co, NM | |
| 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, O | THER | DATA | |
| ype of Submission Type of Action | | | |
| _ | Abandonment Change of Plans Recompletion. New Construction | | |
| Subsequent Report Plugging Back Non-Rout | | | |
| Casing Repair Water Sh | | | |
| Final Abandonment Altering Casing Conversi | | | |
| X Other - Restimulation | | _ | |
| 13. Describe Proposed or Completed Operations | | | |
| 1. Pull 1" tubing. | | | |
| 2. Clean out to PBTD. | | | |
| 3. Acidize and foam fracture treat PC zone (2186'-2216'). | | | |
| 4. Clean out. | | | |
| 5. Run Tubing. | | | |
| 6. Return well to production. | | | |
| Please provide surface stipulations. | | | |
| | | | |
| 14. I hereby certify that the foregoing is true and correct. | | | |
| Signed May ale Title Regulatory Administrator | Dat | e 1/9/01 | |
| (This space for Federal or State Office use) APPROVED BY | | W/12/02 | |
| CONDITION OF APPROVAL, If any: | | 1/10/01 | |

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to ma department or agency of the United States any false, fictitious or fraudulent statements.