

James W. Maness

DRILLING CONTRACTOR

1091 Chaco


XXXXXXXXXXXXXXXXXXXX

DA 5-5828

FARMINGTON, NEW MEXICO

September 4, 1973

United States Department of the Interior
Geological Survey
Southern Rocky Mountain Area
Petroleum Club Plaza
Farmington, New Mexico 87401



Dear Sir;

Navajo II #1

Enclosed are the maps and plat for the development and drilling of the Jerry McCutchin well in Section 31, Township ²⁹~~31~~ North Range 16 West, San Juan County New Mexico.

1. Existing roads including location of the exit from the main highway.

Attached is a map showing roads, pipelines, and telephone lines. No New roads will be built and very minor repairs on existing roads. Only new road is one (100') hundred feet.

2. Planned access roads.

There will be no construction. The new road will be used as in present condition.

3. Location of existing wells.

See map of existing wells.

4. Lateral roads to well locations.

See Map.

5. Location of tank batteries and flow lines.


Unable to determine tank battery location until production is determined.

6. Location and type of water supply (rivers, creeks, lakes, ponds, well, etc.).

Water will be acquired from the San Juan River or Chaco wash over existing roads.

7. Method for handling waste disposal.

All waste material (Cuttings, Garbage, trash etc.) from the drilling will be disposed of in the pit and covered upon completion of the well.



2. Location of cover.

Not applicable

3. Location of airstrip.

Not applicable

10. Location of layout to include position of the pit, trench, ditches, etc., and location of equipment.

See attached plot of location for position of equipment.

11. Plans for restoration of the surface.

Top soil will be stock piled from digging the pit. Upon completion of hole top soil will be used to restore the surface and reseded to required specifications.

12. Any other information that may be used in evaluating the location or equipment. Include general description of the area, nearby, vegetation, and other aspects of the area.

This location is a slight slope to the Northeast. There is no cut to be made, only leveling for the pit and ditches. There is very little vegetation on the soil in this area.

Sincerely,

Jerry McCutchin

by

JAMES H. MANESS
James H. Maness, Agent

5.9 mi
to
US
666

