

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
14-20-0603-9591

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

North Hogback 1

9. WELL NO.

19

10. FIELD AND POOL, OR WILDCAT

Slickrock-Dakota

11. SEC., T., R., N., OR BLK. AND
SURVEY OR AREA

Sec. 1, T29N, R17W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Raymond T. Duncan

3. ADDRESS OF OPERATOR

1777 South Harrison St., P-1, Denver, CO 80210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface
2400' FSL - 2350' FEL
Sec. 1, T29N, R17W

RECEIVED

APR 11 1986

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, NT, GR, etc.)

4982' GR

BUREAU OF LAND MANAGEMENT

FARMINGTON RESOURCE AREA

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned as follows:

1. Pulled rods and tubing.
2. Filled 4½" casing and squeezed into formation with 55 sx class "B" neat cement (total cement slurry 64.9 cu.ft.).
3. Dug down around casing and cut off 4' below ground level.
4. Welded ½" steel plate on casing.
5. Restored surface.

*Note: Cementing witnessed by Mark Philliber with Farmington BLM office.
No dry hole marker - this well located in cultivated field.
Job complete 4-9-86.

RECEIVED

APR 21 1986

OIL CON. DIV.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim L. Jacobs

TITLE Geologist

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

NMOCC

APPROVED
AS AMENDED

DATE

APR 17 1986

AREA MANAGER