



ENERGY, MINERALS and NATURAL RESOURCES DIVISION  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE



BRUCE KING  
GOVERNOR

September 10, 1993

ANITA LOCKWOOD  
CABINET SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

Mr. Scott Daves  
Meridian Oil Inc.  
PO Box 4289  
Farmington, NM 87499

RE: MOI Lloyd A #3, H-09-29N-11W  
Bradenhead Testing

Dear Mr. Daves:

The enclosed copy of the 1993 Bradenhead Test on the referenced well indicates it has a casing failure or was improperly tested. The well is a PC-Chacra Dual with parallel strings of 2-7/8" casing cemented in place. If you choose to retest the well notify this office at least 24 hours prior to testing so that we may provide a witness. If you determine the well has a casing failure you should initiate remedial activity as soon as possible.

Yours Truly,

Charles Gholson  
Deputy Oil & Gas Inspector

xc: Bradenhead File  
Well File