

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

1. LEASE DESIGNATION AND SERIAL NO.

079511-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Florance

9. WELL NO.

50

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 14, T30N, R8W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

1. OIL ☐ GAS ☒ OTHER ☐

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
1860 Lincoln St., Suite 1200, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1667 FHL and 1916 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

6459 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

RECYCLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PURPOSE OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-3-75 MIRUPU and NUBOP.

WIH to 4240', set ret., cement below ret. with 400 sacks Class A neat cement.
Placed 75' cement on top of cement ret.

10-9-75 WIH to 3915 and cut off 7" casing.

10-10-75 Laid down 72 jts 7" casing.

10-11-75 Laid down 123 jts 7" casing. Pumped 35 sx cement plug from 3941-3841. Removed BOP and csq. spool.

10-12-75 Pumped 50 sx cement plug from 2560-2390.

Pumped 50 sx cement plug from 1560-1390.

10-13-75 Cut 8 5/8" csg. @ 350'. Laid down 9 jts 3 5/8" csg.

Pumped 65 sx cement plug from 385-270 settled lower.

Pumped 75 sx cement plug from 350-250.

Pumped 100 sx cement plug from 135- to surface.

Installed dry hole marker and cleaned up area by filling pits, levelling location and cleared location of junk.

18. I hereby certify that the foregoing is true and correct

SIGNED

Production Clerk

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side