State of New Mexico	Form C-103
Submit 3 Copies to Appropriate District Office Energy, Minerals and Natural Resources Department	Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O.Box 2088	WELL API NO. 3004522025
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE X 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	FLORANCE
OIL GAS WELL OTHER	0.37.43
2. Name of Operator Attention: Amoco Production Company KELLY STEARNS	8. Well No.
3. Address of Operator P.O. Box 800 Denver Colorado 80201	9. Pool name or Wildcat Blanco Mesaverde
4. Well Location Unit Letter F : 1703 Feet From The NORTH Line and 18	50 Feet From The WEST Line
20N 5 9M N	IMPM SAN JUAN County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	MFM SAN SOAN COUNTY
11. Check Appropriate Box to Indicate Nature of Notice, Re	port or Other Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEN	MENT JOB
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, i work) SEE RULE 1103.	ncluding estimated date of starting any proposed
THE CATHODIC PROTECTION WELL ASSOCIATED WITH THE ABOVE WELL WILL BI ATTACHED PROCEDURE.	E PLUGGED AND ABANDONED PER THE
VERBAL APPROVAL RECEIVED FROM ERNIE BUSCH ON 11-23-93.	REGETVE PO NOV2 9 1993
	OIL CON. DIV.
	DIST. 3
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Kelly Strand TITLE BUSINESS A	ANALYST 11-22-1993
TYPE OR PRINT NAME KELLY STEARNS	TELEPHONE NO. (303) 830-4457
(This space for State Use)	
ADDROVED BY TIME BANK TITLE	DEC - 1 1993
APPROVED BY THE TILLE	DATE

GROUND BED ABANDONMENT

WELL NAME:	-Florance #321	9
LOCATION:	Sec 15-30-8	

- 1) Weld 6 " dia. spool with diverter line to pit
- 2) MIRU
- 3) Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free. Wash hole to TD 4.
- 4) Pump * sx of neat cement w/ 1/4 lb. sk. Flocele.
 Pull out work string.
- 5) Top off hole with cement, set flexible pipeline marker as PxA marker.
- 6) RDMO

* Sacks of cement = (dia.)2xT.D.x.00693 where dia. is in inches, TD is in feet

JAB.GRA

NOV2 9 1993 OIL COL