biocagaro, tuffajaroki jaten sala

## UNITED STATES DEPARTMENT OF THE INTERIOR

<b>5. LEASE</b> SF 078	3730	ۇ. س	ë.	
6. IF INDIAN,	<del></del>	R TRIE	BE NAME	
	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		:	
7. UNIT AGRE				
San Juan	30-5 U	nit	1 1	
8. FARM OR L			-	
San Juan	30-5 0	nıt	· · ·	
9. WELL NO. #51	, <del>,</del> , , , , , , , , , , , , , , , , ,	7		
10. FIELD OR W	/ILDCAT NA	ME	- 1. - 1.	
Basin I	akota)	-	경관 즉	
11. SEC., T., R., M., OR BLK. AND SURVEY OR				
AREA	<u>.</u> . =	5	i	
Sec 21	T30N.	Ř51	<b>7</b>	
12. COUNTY OF	RPARISH	13. ST	ATE	
Rio Arr	iba ]	~ N ∈	w Mea	kico
14. API NO.	\$ jakij		5 4 4 4	
30-039-	22447	्प् '	<u> </u>	
15. ELEVATION	S (SHOW I	OF, KD	B, AND	WD)
64141 GE	gradient de la	· ,		

**GEOLOGICAL SURVEY** SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)  $\mathbf{k}$ other well well 2. NAME OF OPERATOR Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR P.O. Box 90, Farmington, N.M. 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 1000' FNL & 1800' FEL AT SURFACE: AT TOP PROD. INTERVAL: Same as above AT TOTAL DEPTH: Same <u>as above</u> 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report reg change g PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON\* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* Sept 28, 1980 TD hole at 0145 hrs. TOH for logs and breaking bit when gas escaping through the blind rams caught fire at 0500 hrs. The 2" kill line was closed. Rig crew received minor burns Put out fire with water and  $N_2$ . Killed well with 150 bbls of water. Spotted 200 sacks cement plug at the bottom of the intermediate casing and displaced with 100 bbls of water. well shut in overnight. Well dead. Sept 29, 1980 Preparing to remove rig. Well is dead. Subsurface Safety Valve: Manu. and Type ... 18. I hereby certify that the foregoing is true and correct Production ClerkTE Oct 1980 TITLE HOUTED FUR HELIUIU
(This space for Federal or State office use) DATE APPROVED BY

CONFIDENTIAL FARMINGTON DISTRICT

CONDITIONS OF APPROVAL, IF ANY: