

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

~~CONFIDENTIAL~~

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Greenwood Holdings Inc.	8. Farm or Lease Name Kirtland
3. Address of Operator 5600 S. Quebec St., Suite 150C, Englewood, CO 80111	9. Well No. No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>1214</u> FEET FROM THE <u>North</u> LINE AND <u>650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>29N</u> RANGE <u>15W</u> NMPM.	10. Field and Pool, or Wildcat Wildcat BASIN FRT 202
15. Elevation (Show whether DF, RT, GR, etc.)	12. County San Juan

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER Plug back and recompletion ☒

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-24-89 RU Halliburton and Big A, TIH w/overshot to retrieve RBP, TOH w/RBP, TIH w/cement retainer, set retainer and load hole @ 4325'.

1-25-89 Pump 20 sx Class B neat cement below retainer, pull up, load hole w/9.2# mud, pump 20 sx Class B neat cement from 3196'-2950', bump plug after 2 hrs, load hole w/9.2# mud to 1290', set plug from 1290'-1390' w/10 sx Class B neat cement, pull up, load hole w/9.2# mud, set plug from 750'-650' w/10 sx Class B neat cement, waited 2hrs & bumped plug.

1-26-89 RU Schlumberger, perforate Fruitland Coal 305'-317', 337'-351', 359'-365' w/4 jts/ft.

RECEIVED  
FEB 01 1989  
OIL CON. DIV  
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operations Manager DATE 1-30-89

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT 3 DATE FEB 01 1989

CONDITIONS OF APPROVAL, IF ANY: