Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

| DISTRICT I P.O. Box 1980, Hobbs, NM 88240 | | | | |
|---|---|---|---|------|
| F.O. Box 1900, 110005, 14141 00240 | OIL CONSERVATIO P.O.Box 200 | | WELL API NO. | |
| DISTRICT II | Santa Fe, New Mexico | | | |
| P.O. Drawer DD, Artesia, NM 88210 | | | 5. Indicate Type of Lease STATE FEE | X |
| DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 | ı | | 6. State Oil & Gas Lease No. | |
| SUNDRY NOT | ICES AND REPORTS ON | WELLS | | |
| | OPOSALS TO DRILL OR TO DEE VOIR. USE "APPLICATION FOR :-101) FOR SUCH PROPOSALS.) | R PERMIT" | 7. Lease Name or Unit Agreement Name | |
| 1. Type of Well: | -101) FOR SUCH PROPUSALS. |) | Crawford Gas Com "B" | |
| OIL GAS WELL | OTHER | | | |
| 2. Name of Operator | Attention: | | 8. Well No. | |
| Amoco Production Company | L | ois Raeburn | ,1E | |
| Address of Operator P.O. Box 800 Denver | Colorado 80201 | (303) 830-5294 | 9. Pool name or Wildcat Basin Dakota | |
| 4. Well Location Unit Letter J :152 | Po Feet From The Sou | th Line and 1 | 520 Feet From TheEast | Line |
| Section 24 | Township 29N | Range 12W | NMPM San Juan Cou | ntv |
| | | ether DF, RKB, RT, GR, etc.) 5632' GL | | |
| | propriate Box to Indicate | Nature of Notice, R | Report, or Other Data | |
| NOTICE OF INT | ENTION TO: | SI | JBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | ALTERING CASING | |
| TEMPORARILY ABANDON | CHANGE PLANS | COMMENCE DRILLING | OPNS. PLUG AND ABANDONMEN | NT |
| PULL OR ALTER CASING | | CASING TEST AND C | EMENT JOB | |
| OTHER: | | OTHER: | Cleanout | _ [× |
| 12. Describe Proposed or Completed Oper work) SEE RULE 1103. | rations (Clearly state all pertinent de | etails, and give pertinent dates, | including estimated date of starting any proposed | |
| HELD OK, RUN CBL 2500' TO CMT TO SURF. DRLG OUT CM TEST CSG TO SURF @ 750#, | 0 200', TOC 1400', PERF IT. TIH SET RBP @ 6089' SE HELD OK , PMP DYE WTR | @ 1350', 2 JSPF, W/ . ET PKR @ 6058'. TEST TO CIRC, PUMP 250 SK | RBP SET @ 6089', TEST CSG TO 7506 50, 2 SHOTS. TO ISOLATE BH L RBP ,HELD OK RELEASE PRK LOAD AN S LEAD CMT, CMT TO SURF OUT BH, TIH W/ PROD TBG TO 3000' RDMO C | D |
| | | | REPERMED. | |
| | | | MENUES WEST | |
| | | | OIL CON. DIV. | |
| I hereby certify that the information above | e is true and complete to the best of | • | DIST. 3 | |
| I hereby certify that the information above | e is true and complete to the best of | f my knowledge and belief. Business A | DIST. 3 | |
| | e is true and complete to the best of LLS W LOIS Raeburn | Business / | Assistant 06-09-1995 | 5294 |
| SIGNATURE Sais M | reburn | Business / | Assistant DATE 06-09-1995 | 5294 |