

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS


(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Tenneco Oil Company 3. Address of Operator P.O. Box 3249, Englewood, CO 80155 4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>790</u> FEET FROM THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>29N</u> RANGE <u>10W</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 5502' gr.	7. Unit Agreement Name 8. Farm or Lease Name Sullivan Frame A 9. Well No. 1E 10. Field and Pool, or Wildcat B. Dakota/B1. Chacra/Und. MV 12. County San Juan
---	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/9/80 - MIRUSU, Kill well w/2% KCL water. Install BOP. POOH w/tbg. Set RBP @ 2990'. Dumped 2 sx of sand on top of BP and PT to 3000 PSI. Test good. Perf'd Chacra 4" chg, gun (2 JSPF): 2721-33', 2811-18', 2824-28' (23', 46 holes). RIH w/fullbore pkr. on 2-3/8" tbg. Left pkr. above top perfs. Set pkr. @ 2780'. Circ'd 500 gals. 15% HCL. Shut bypass, acidized down tbg. w/500 gals. 15% HCL and 33 balls. Released pkr. and knocked balls off perfs. Blew hole dry w/N₂ thru bypass. POOH w/tbg. and pkr. Frac'd Chacra w/70% quality foam, 568 bbls. water, 5498 gals. flush and 80,000# 20/40 sand. AIR: 20 BPM, AIP: 1525 PSI, ISIP: 1500 PSI, PSIP: 1500 PSI, flowing thru 1/2" choke. Flowing to clean up. Kill well w/2% KCL water. RIH w/tbg. and retrieving head, BP, POOH w/tbg. & BP. RIH w/2-3/8" beveled collar tbg., muleshoe, F nipple, seal assy., and blast jts. Tagged sand @ 4395'. Cleaned sand off pkr. w/foam. Knocked out expendable plug.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Frank T. Chavez</u>	TITLE <u>Asst. Div. Adm. Mgr.</u>	DATE <u>1/8/81</u>
APPROVED BY <u>Original Signed by FRANK T. CHAVEZ</u>	TITLE <u>SUPERVISOR DISTRICT #3</u>	DATE <u>JAN 10 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		