

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒
2. NAME OF OPERATOR Southland Royalty Company
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 930'S, 1770'E

RECEIVED

14. PERMIT NO. AUG 01 1986 15. ELEVATIONS (Show whether DF, ST, GR, etc.)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3, T-29-N, R-10-W N.M.P.M.
12. COUNTY OR PARISH San Juan 13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This location is ready for final inspection.

ACCEPTED FOR RECORD

AUG 04 1986

RECEIVED

AUG 05 1986

OIL CON. DIV.
DIST. 3

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO
[Signature]

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Drilling Clerk DATE 08-01-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOCC



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Caller Service 4104
Farmington, New Mexico 87499

IN REPLY REFER TO:
SF-076958 (WC)
3162.5-1(a) (016)

APR 02 1986

RECEIVED

APR 3 1986

FARMINGTON DISTRICT

Southland Royalty Company
P. O. Drawer 570
Farmington, NM 87499


Gentlemen:

A recent inspection by members of my staff showed that the following work needs to be done to bring your lease No. SF-076958 into compliance:

1. The road that parallels the main road and connects your No. 13 Hare well located 990' FSL and 1830' FEL and No. 15 Hare well located 930' FSL and 1770' FEL, both in sec. 3, T. 29 N., R. 10 W., needs to be reclaimed. The road needs to be ripped, disked, and bermed on both ends. It needs to be seeded with BLM Seed Mix No. 2 between July 1 and September 15, 1986.

If you have any questions, please contact any member of the Fluids Surface Management Staff at (505) 325-4572.

Sincerely,


John S. McKee
Acting Area Manager



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Caller Service 4104
Farmington, New Mexico 87499

IN REPLY REFER TO:
SF-076958 (WC)
3162.5-1(a) (016)

APR 02 1986

RECEIVED

APR 3 1986

FARMINGTON DISTRICT

Southland Royalty Company
P. O. Drawer 570
Farmington, NM 87499


Gentlemen:

A recent inspection by members of my staff showed that the following work needs to be done to bring your lease No. SF-076958 into compliance:

1. The road that parallels the main road and connects your No. 13 Hare well located 990' FSL and 1830' FEL and No. 15 Hare well located 930' FSL and 1770' FEL, both in sec. 3, T. 29 N., R. 10 W., needs to be reclaimed. The road needs to be ripped, disked, and bermed on both ends. It needs to be seeded with BLM Seed Mix No. 2 between July 1 and September 15, 1986.

If you have any questions, please contact any member of the Fluids Surface Management Staff at (505) 325-4572.

Sincerely,


John S. McKee
Acting Area Manager