

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Tenneco 3. Address of Operator P.O. Box 3249, Englewood, CO 80155 4. Location of Well UNIT LETTER C 725 FEET FROM THE North LINE AND 115 FEET FROM West LINE, SECTION 25 TOWNSHIP 29N RANGE 11W NMPM.	7. Unit Agreement Name 8. Farm or Lease Name Bruce Sullivan Com B 9. Well No. 1 10. Field and Pool, or Wildcat Blanco Mesaverde/B1 Chacra 12. County San Juan
15. Elevation (Show whether DF, RT, GR, etc.)	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/17/80 Spud 13 3/4" hole 11/16/80 run 6 Jts 9 5/8" Csg. Set @ 267' KB. cmt w/ 200SX CL-B and 2% CACL2 w/ 1/4# per sk. Flocele. CMT top 8-10' Below ground level after displacement. WOC NUBOP Test to 1000 PSI for 30 mins. OK CMT Backside w/60SX CL-B w/ 4% CACL2. Fill 25' of hole WOC 7 Hrs. Drill out, reduce hole 8 3/4" and Drill ahead.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Carly Statham</u>	TITLE <u>Asst. Div. Adm. Mgr.</u>	DATE <u>11/26/80</u>
Original Signed by FRANK T. CHAVEZ		SUPERVISOR DISTRICT # 3
APPROVED BY _____	TITLE _____	DATE <u>DEC 9 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		