Form 3160-5

UNITED STATES

FORM APPROVED Budget Bureau No. 1004-0135

Completion or Recompletion Report and Log form.)

(Julie 1990)	DEPARTMENT OF	THE INTERIOR		Expires: March 31, 1993
	BUREAU OF LAND	MANAGEMENT	RECEIVED	6. Lease Designation and Serial No.
	SUNDRY NOTICES AND	DEDODTO ON W	DI M	NM-014378
	6. If Indian, Allottee or Tribe Name			
Do not use this form	n for proposals to drill or to	o deepen or reentry	to a different reservoir.	
USE	"APPLICATION FOR PER	MII — " for such pa	apesais O All 3 93	
	SUBMIT IN T	RIPLICATE 31	9 FARMINGTON, N.M.	7. If Unit or CA, Agreement Designation
1. Type of Well				†
Oil K Gas [8. Well Name and No.			
2. Name of Operator	H.J. Loe Federal B #2E			
Texaco Explorati	9. API Weil No.			
3. Address and Telephone No.	30-045-24554			
3300 N. Butler, 1	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, S	Fulcher Kutz			
1700' FNL & 1	11. County or Parish, State			
Sec. 23, T29N,	R12W			
, ,				San Juan
12. CHECK AP	PROPRIATE BOX(s) TO	INDICATE NATUR	RE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SU	TYPE OF SUBMISSION TYPE OF ACTION			
X Notice of In	tent OFAR	Abandonmen	ıt	Change of Plans
	ECEIA	Recompletion		New Construction
Subsequent I	2712	Plugging Bac		Non-Routine Fracturing
				Water Shut-Off
Final Abando	SEP 3 1992	Altering Cas		Conversion to Injection
		Other		Dispose Water

DIST. 3 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco E. & P. Inc. proposes to recomplete the subject well in the Pictured Cliffs formation. Upon completion the well will produce dually with the Dakota formation. The following procedure will be followed:

- 1. MIRUSU, NDWH, NUBOP.
- 2. POOH w/ production TBG, TIH w/ RBP and TBG, set RBP above Dakota perfs. POOH w/ TBG.
- 3. RU wireline, RIH w/ perf gun and perf Pictured Cliffs intervals (1632'-1650') using 4 JSPF. RD wireline.
- 4. RIH w/ TBG and PKR, set PKR above PC perfs, and flow test well, swab dry when necessary.
- 5. Following flow test RU slickline and RIH w/ 7 day press bomb. Set bomb at mid-pay, SI well, run buildup.
- 6. Following buildup test, POOH w/ slickline, RU Service Co. and fracture PC formantion. Flow/swab load.
- 7. RIH w/ dual production equipment, set PKR between formations, RDMOSU.

14. I hereby certify that the foregoing is true and correct Signed	Area Manager	Bate 8/24/92
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	AREA MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



H. J. LOE FEDERAL B No. 2E PROPOSED COMPLETION

WELL:

H. J. Loe Federal B No. 2E

LOCATION:

Unit E, 1700' FNL & 1050' FWL SW/4, NW/4, Sec. 23, T29N, R12W

Sen Juen County

SPUD DATE:

10-18-60

COMPL DATE:

12-31-90

FORMATION TOPS:

Fruitiand 1382'
Pictured Cliffs 1632'

Chacra 2681'

Cliffhouse 3224'

Menefee 3396'

Pt. Lookout 4068

Mancos 4404'

Gallup 5326'

Greenhorn 6085'

Graneroe 6142'

Dekota 6196'

PROPOSED PERFS: PICTURED CLIFFS

1632' - 1650'

DAKOTA PERFS:

61 66' - 6290'

PBTD - 6312' TD - 6340'

