

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-014378

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

TEXACO Inc. Attention: G. L. Eaton

3. ADDRESS OF OPERATOR

P. O. Box 2100, Denver, Colorado 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

SW 1/4 Sec. 23

1100' FSL & 2000' FEL, Sec. 23

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5595' KB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Texaco

H. Loe - Federal "B"

9. WELL NO.

3E

10. FIELD AND POOL, OR WILDCAT

basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 23 T29N-R12W

12. COUNTY OR PARISH

13. STATE

San Juan

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Ran Production Casing

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Ran 6282' (148 joints) of 4-1/2" OD 10.5# 8rd J-55 ST&C casing. Landed at 6278' KB. Cemented first stage with 1100 sacks 50-50 pozmix, 2% gel, 6-1/4 gilsonite and 100 sacks class "B". Plug down at 9:30 AM, 10-15-80. Cemented second stage with 1250 sacks Howco Lite with 12-1/2# gilsonite per sack. Cement to surface. Plug down at 3:30 PM, 10-15-80. Released rig at 7:00 PM, 10-15-80.

DV tool set at 3264'.



18. I hereby certify that the foregoing is true and correct

SIGNED SIGNED: G. L. EATON

TITLE District Superintendent DATE Nov. 6, 1980

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

USGS(5) OGCC(2) GLE ARM(2)

Farmington Aztec

BY RW

*See Instructions on Reverse Side