UNITED STATES	5. LEASE	
DEPARTMENT OF THE INTERIOR	SF 080247	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
	Florance	
1. oil gas well well well other	9. WELL NO.	
2. NAME OF OPERATOR	117E	
Tenneco Oil Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Basin Dakota	
P. O. Box 3249, Engelwood, CO 80155	11. SEC., T., R., M., OR BLK. AND SURVEY OF	₹
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	
holow)	Sec. 35, T29N R9W	_
AT SURFACE: 1780' FNL 990' FEL "H"	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	San Juan New Mexico	
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	5665' gr.	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	The same of the sa	
FRACTURE TREAT US SHOOT OR ACIDIZE US US STANDARD		
REPAIR WELL	(NOTE: Report results of mulAP Rolling of erizer	ıe
PULL OR ALTER CASING	change on Form 9-330.)	
MULTIPLE COMPLETE	OIL CON. CON.	1
CHANGE ZONES	DIST. 3	ACT.
ABANDON* (other) Commence drilling operations	and the second s	•
		_
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	te all pertinent details, and give pertinent date	S,
including estimated date of starting any proposed work. If well is c	at to this work *	
measured and true vertical depths for all markers and zones pertine	rc. RU and run 8 jts 9-5/8" 36	#
csg set @ 324'. Cmt w/250 sx Class B w/2% CACL	. WOC. Tail in w/50 sx Class	В.
Cir to surface. WOC. Drill out and ahead.	2	
Cir to surface. Woc. Bill out and another	a good hole RII and run 7 its 2	3#
4/12/81 - Drill to 2750'. Short trip. Circ and	on impression block.	
csg. Hit bridge. POOH. Laid down csg. Wait	on impression brooks	
4/15/81 - GIH w/taper mill, straightened csg, 1:	ipped guide shoe and started	
4/15/81 - GIH W/taper mill, Stranghtened 55, 2 running csg. Run 62 jts (2773') of 7" 23# csg	set @ Z/SU . CMT W/SU SX 30/30	

POZ and 4% get. Tail w/150 sx Class B and 2% CACL $_2$ PD. Good returns. Set slips,

cut off csg. WOC. 4/20/81 - Drill to TD @ 6635' 4/19/81. POOH. Log. RU and run 93 jets of 4-1/2" 10.5# csg. Hung w/shoe @ 6605', hanger @ 2572'. Cmt w/315 sx 65/35 POZ, 6% gel, 6% D-60 and 4% D-13. Tail w/150 sx Class B. Plug down. Reserve out. Good returns. Laid down drill pipe. _ Set @ _____ Ft. Subsurface Safety Valve: Manu. and Type _

18. I hereby certify that the foregoing is true and correct

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

SIGNED

TITLE _

ACCEPTED FOR RECORD

NMOCC

APR 29 1981

"See Instructions on Reverse Side

FARMINGTON DISTRICT