State of New Mexico Submit 3 Copies to Appropriate District Office DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				Form C-103 Revised 1-1-89	
			WELL API NO. 30045248/68		
			5. Indicate Type of Lease	5. Indicate Type of Lease	
			STATE FEE X 6. State Oil & Gas Lease No.		
(DO NOT USE THIS FORM FOR PI DIFFERENT RESE (FORM 1. Type of Well:	TICES AND REPORTS ON TROPOSALS TO DRILL OR TO DEEL REVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A PERMIT"	7. Lease Name or Unit Ag		
OIL GAS WELL	X OTHER				
2. Name of Operator Amoco Production Company	1 1101111111		8. Well No.		
3. Address of Operator P.O. Box 800 Denver	Colorado 80201	(303) 830-5294	9. Pool name or Wildcat Basin Dakotta		
4. Well Location Unit Letter N : 11	10 Feet From The Sout	h Line and 1			
Section 27	Township 29N	Range 12W	NMPM San Ju	an County	
	10. Elevation (Show when	ther DF, RKB, RT, GR, etc.)	Awar war Sun	an County	
11. Check An	propriate Roy to Indicate	5338' GL	lanart a Otl D		
Check Appropriate Box to Indicate Nature of Notice, F NOTICE OF INTENTION TO:			BSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	G CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AN	D ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB		
OTHER: Bradenhead & Csg Rep X OTHER:				Г	
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all pertinent deta	ails, and give pertinent dates,	including estimated date of starti	ng any proposed	
Amoco Production Company r	equest permission to repair Br	adenhead and repair Ca	sing leak in subject well.	en diamakan di sambaga ayang makan di dagan kangan	
			Pina.		
See attached procedures			DEC N APR	EIVED 1 0 1995	
)M. DIV. 37. 3	
I hereby certify that the information above	re is true and complete to the best of m	ny knowledge and belief.	The second second second		

DATE 04-07-1995 Lachum SIGNATURE Lois Raeburn TYPE OR PRINT NAME TELEPHONE NO. (303) 830-5294

(This space for State Use)

hnny Robinson

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE APR

CONDITIONS OF APPROVAL, IF ANY:

Gallegos Canyon Unit Com B #1E TD = 6016', PBTD = 5961' Page 2 of 2

OCD

- 1. Contact B≥M prior to starting repair work.
- 2. Catch gas sample off of braden head and casing, have analyzed.
- 3. Test anchors, install if necessary. MISURU.
- 4. Blow down and kill well if absolutely necessary kill with 2% KCL
- 5. Issolate Dakota with Wireline BP.
- 6. TIH with RBP X Packer. Hunt for leak. (Suspected in the Mesa Verde)
- 7. Issolate leak. Dump sand on top of RBP.
- 8. Spot Cement plug across failure. Pressure up cement.
- 9. TOH. Find Cement Top with CBL Log.
- 10. Perforate with 4 JSPF above TOC. Establish circulation w/ water.
- 11. Mix and pump cement for squeeze. (A cement retainer or packer might be needed).
- 12. Let cement set. TIH with bit and scraper and DO cement. Pressure test casing to 1000 psi. TOH.
- 13. TIH. Circulate sand off RBP and TOH with RBP.
- 14. TIH with standard assembly land intake at 5,900'. Clean out fill if present.
- 15. RDMOSU. Return to production. Swab in if necessary.