## State of New Mexico

Form C	-103
Revised	1-1-8

Submit 3 Copies to Appropriate	Energy, Minerals and Natural Resources Department				Revised 1-1-89	1
District Office  DISTRICT I P.O. Box 1980, Hobbs, NM 88240	TRICT I  OIL CONSERVATION DIVI					
· · ·	ŀ	P.O.Box 2088		WELL API NO.	4524885	
DISTRICT II P.O. Drawer DD, Artesia, NM 882	Santa Fe, N	lew Mexico 87	7504-2088	5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 8	7410		STATE FEE X  6. State Oil & Gas Lease No.			
SUNDRY N						
l e e e e e e e e e e e e e e e e e e e	PROPOSALS TO DRILI SERVOIR. USE "APPLI M C-101) FOR SUCH P		7. Lease Name or Unit	se Name or Unit Agreement Name		
1. Type of Well:	W C-101) TON SOCH F	NOT USALS.	The second secon	- Whit	e Gas Com	
OIL GAS WELL	X OTHER					
2. Name of Operator		Attention:		8. Well No.	4 =	
Amoco Production Company  3. Address of Operator		Patt	y Haefele		1 E	
P.O. Box 800 Denver	Colorado	80201	(303) 830-4988	9. Pool name or Wildo Bas	at in Dakota	
4. Well Location Unit Letter G :	1500 Feet From The	North	Line and 21	20 Feet From The	East	Line
Section 22	Township	29N R	ange 13W I	NMPM Sar	n Juan 💢	County
	10. Eleva	ation (Show wheth	er DF, RKB, RT, GR, etc.) 5334' KB			
II. Check	Appropriate Poy	to Indianta N		anort or Other D	a ta	
Check	Appropriate Box ( INTENTION TO:	io maicate i	Nature of Notice, Re	BSEQUENT REPOR		
	٦			<u></u>		Γ
PERFORM REMEDIAL WORK	」 PLUG AND ABAI	NDON []	REMEDIAL WORK	ALTE	RING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING	_		CASING TEST AND CE	MENT JOB		
OTHER: Ground Bed A	Abandonment	×	OTHER:			[
12. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state	all pertinent deta	ils, and give pertinent dates,	including estimated date o	f starting any propos	sed
Amoco Production Co	ompany has perform	ned a ground	bed abandonment asso	ciated with the above	ve well.	
MIRUSU 12/5/95. Consider the back fill hole, dug pit with wire spear to 60° hammer. Drill with counit. RIH and plug grants.	and spot rig. Latch, remove 2 anodes. one bit to 210' - get	anode wires Remove wire ting shale bac	7 ea, jet out coke bree e to 160', jetted to 185 ck. Drill with cone bit	eze to 160' - unable b'. Cleaned anodes to 210', hole clean.	to make hole. To 200' with air Rig up coil tul	ΓIH
				MAR - 1 188	is Ü	
				OM CON	MAG	
I hereby certify that the information	above is true and complet		Staff Ass	sistant DIVIL 3	ニンロ <b>U</b> o 02-29-199	96
TYPE OR PRINT NAME	Patty Haefele		TITLE		PHONE NO. (303) 8	
(This space for State Use)	,			AGLE		
	D BY ERNIE BUSCH		THLE PUTY OIL & GAS II	NSPECTOR, DIST. #3	MAR -	4 19