Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR

5.	LEASE
	NM-012711

NM	1-01	271	1	

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) $ \frac{1}{2} \left(\frac{1}{2} - \frac{1}{2} + \frac{1}{2}$	8. FARM OR LEASE NAME		
1 -11	Lawson		
well gas well other	9. WELL NO.		
2. NAME OF OPERATOR	<u>l</u> R		
Tenneco Oil Company	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR P. O. Box 3249, Englewood, CO 80155	Mesaverde-Basin Dakota		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
helow)	Sec. 10, T30N R8W		
AT SURFACE: 2400' FSL 1150' FWL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan NM		
	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6242' gr.		
TEST WATER SHUT-OFF	VED / Sign		
FRACTURE TREAT			
SHOOT OR ACIDIZE REPAIR WELL MARY COMMANDER SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone		
PULL OR ALTER CASING T	change on Form 9-330. kg (5) 1 1 1 1 1 1		
MULTIPLE COMPLETE CHANGE ZONES CHANGE ZONES CHANGE ZONES CHANGE ZONES	AL SURVEY		
CHANGE ZONES	CIL CON. COM.		
(other)			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined 2/18/82 - RIH w/tbg & 2-7/8" swedge on btm & SN.	directionally drilled, give subsurface locations and nt to this work.)* Tagged SD 3 5460'. CO to model D		
pkr $w/N2$ & foam. Pld up to 5360' & landed tbg i			
around w/N2. Made 1 swab run & well started flw	g.		
2/19/82 - Well flwg gas mist. 2/20/82 - Flwg to CU.			
2/23/82 - Killed well w/1% KCL wtr. POOH w/tbg.	PIH W/WI and sot PPD & 4950! Dumped		
2sx SD on top of RBP and loaded hole w/2% KCL wt	r. Perf'd Chacra w/4" csg gun and 2		
JSPF as follows: 4650-55', 4777-81', (9' - 18 h			
2/24/82 - RIH w/tbg and 7" fullbore pkr to 4694'	. Acidized dn tbg w/200 gal 15% wtd		
HCL and 12 ball slrs. Brk dn @ 1500 psi. Did n	ot get complete ball off. Knocked		
balls off w/pkr and unloaded hole w/N2. Frac'd	Chacra dn csg w/70% quality foma w/2%		
KCL wtr and $20/40$ SD. Flushed to top perfs. Ra $2/25/82$ - Ran GR over Chacra perfs. RIH w/tbg	n RA SD in last stage of frace.		
N2 and foam. Landed tbg @ 4633'. Removed BOP & Subsurface Safety Valve: Manu. and Type	install WH. Kicked well around w/N2.		
18. I hereby certify that the foregoing is true and correct	Fiwg to Cu. RDMOSU.		
SIGNED TITLE PROJUCTION TITLE PROJUCTION AND	DATE STATE		
(This space for Federal or State of	fice use)		
APPROVED BY TITLE	DATE		
CONDITIONS OF APPROVAL, IF ANY:	 -		

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

MAR 10 1982



FARMINGTON DISTRICT