

REPORT

The Deviation on the Hatch #1 as reported by Y W Drilling Company were as follows:

<u>Depth</u>	<u>Deviation</u>
322'	$\frac{1}{2}^{\circ}$
1642'	$1\frac{1}{2}^{\circ}$
2821'	$1\frac{1}{4}^{\circ}$
3732'	1°
4700'	$1\frac{1}{4}^{\circ}$

R. E. Lauritsen
R. E. Lauritsen, Operator

STATE OF NEW MEXICO,)
) ss.
COUNTY OF SAN JUAN.)

This Report was subscribed and sworn to before me this
23 day of June, 1981, by R. E. Lauritsen.

Kay S. Coggins
Notary Public

My Commission Expires:

SEPT. 24, 1984

