

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-7122	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator		
RCO Oil and Gas Company, Division of Atlantic Richfield Company		
Address of Operator		
P. O. Box 5540, Denver, Colorado 80217		
Location of Well		
UNIT LETTER <u>E</u> <u>1850</u> FEET FROM THE <u>North</u> LINE AND <u>800</u> FEET FROM		
THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		
5679' GL		
12. County		
San Juan		

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>		COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <u>N.O. setting production casing</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled to 6630'. Logged. RU & ran 146 jts 5-1/2", 17#, K-55, ST&C casing and landed @ 6629'. Pump 20 bbls sweep followed by 185 sx 50/50 pozmix with 2% gel and 6-1/4#/sx gilsonite and defoamer, followed by 144 sx Class "B" cement with 6-1/4#/sx gilsonite & defoamer. Pumped 10 bbls sweep followed by 740 sx 50/50 pozmix with 2% gel & 6-1/4#/sx gilsonite & defoamer followed by 60 sx Class "B" neat cement. Bumped plug.

Released rig @ 7:00 pm 1-13-82.

WO Completion.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W.A. Walther, Jr.</u>	TITLE <u>District Manager of Production</u>	DATE <u>2-2-82</u>
Original Signed by FRANK T. CHAVEZ		
APPROVED BY	SUPERVISOR DISTRICT <u>3</u>	DATE <u>FEB 5 1982</u>
CONDITIONS OF APPROVAL, IF ANY:		