+Submit 3 Copies to Appropriate

(this space for State Use)

State of New Mexico Energy, Minerals and Natural Resources Department

Form C 103 Revised 1-1-89

District Office	-								
DISTRICT I P.O. Box 1980, Hobbs, NM S8240	OIL CONSERVATION DIVISION				WELL API NO.				
1. O. DUA 1760, 110003, 1411 002 10	P.O. Box 2088 Santa Fe, New Mexico 87504-2088			30-045-25147					
P.O. Drawer DD, Artesia, NM 88210	Junu	-,		* *	5. Indicate Type	of Lease STATE	FE	E 🗌	
DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410						as Lease No.			
						E 7122			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE *APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)						or Unit Agreement	/////// Name	! 	
1. Type of Well: Oil Well Gas Well Well	1	OTHER				State A Gas Co	om		
2. Name of Operator	<u> </u>				8. Well No.	# 1E			
Conoco Inc.					9. Pool name o		-		
3. Address of Operator 10 Desta Dr. Ste 100W, Midla	and. Tx., 79705	j - 4500				Basin Dakota 71	1599		
4. Well Location	110, 17,, 10.00								
Unit Letter E 1850	Feet From T	heNo	orth	Line and	800 Feet F	rom The	West	Line	
Section 36	Township	29 North	Ran	₃e 11 West	NMPM	San Juan		County	
Section 30				F, RKB. RT, GR, ctc.)		111111111	////////	111111	
<u>/////////////////////////////////////</u>	//////////////////////////////////////	Don to Ind	iosto N	5679' GL	Penort or Ot	ner Data	<u>,,,,,,,,</u>	<u> </u>	
			icate in	ature of Notice	e, Report, or Ot UBSEQUENT)F·		
NOTICE OF IN	HENHONI	O .		3	ODOLQOLITI	7		Г	
PERFORM REMEDIAL WORK	PLUG AN	D ABANDON		REMEDIAL WORK	<u></u>	ALTERING C	ASING	L	
TEMPORARILY ABANDON	CHANGE	PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND A	ABANDON	MENT L	
PULL OR ALTER CASING				CASING TEST AN	D CEMENT JOB				
	ntegrity Test			OTHER				[
12. Describe Proposed or Completed work) SEE RULE 1103.							proposed		
It is proposed to perform a casing	; integrity test a	to temporar	illy abali	don uns wen dan	S ulo tono unis P	en e			
1. Pull tbg & run a RTBP set @	6100 TEDP	ert po 450	22 Ki	TAP within!	<i>00'</i>				
2. Fill wellbore w/ corrosion inhi	biting water & p	ressure test t	to 500 p	sig.	or many constants of	en meneral (d. 1981) 198 geret	જ ઉ‴ત્		
3. Rig down, move off									
					M on	ACTOR			
					E 77 001	- 0 ld\$/	200		
						GOM. D DITL 3	IV.		
12. I hereby certify that the information above	is true and complete to	the best of my kno	owiedge and		gulatory Agent	DATE	October	6, 199°	
SIGNATURE	(11 mm//		TIT	LE				CE 40	
TYPE OR PRINT NAME Kay Maddox						TELEPHO	ne no. 686	-0348	

conitions of approval, if any: A ANON to 11-15.97

A B Noted Above

NOTIFY AZTEC OCD
IN TIME TO WITNESS.

DEPERTY OF A GAS INSPECTOR, DIST. 43