UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Noti	ces and Reports on Wel	lls	•	
				5.	Lease Number
					SF-080724-A
Type of Well				6.	If Indian, All. or
GAS					Tribe Name
			_	7.	Unit Agreement Nam
Name of Operate	or				
RESOUR	GTQN				
RESOUR	CES OIL 8	GAS COMPANY			
			_	8.	Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700				۵	Zachry #28 API Well No.
PO Box 4289,	rarmington, NM	0/433 (303) 326-3/00		J.	30-045-25194
. Location of We	11 Footage Se	C. T. R. M	_	10	Field and Pool
		29-N, R-10-W, NMPM			Armenta Gallup
TOOU FOLL, 330	100, Dec.33, 1-	as his to his matri		11.	County and State
					San Juan Co, NM
	Abandonment	Casing Repair Altering Casing X Other - Tubing r			o Injection
3. Describe Pr	roposed or Compl RU. TOOH w/pump H w/bit. Circ &	Altering Casing	Convers epair P. TOOH w/2 TOOH w/bit.	3/8"	tbg. SD for weekenw/190 jts 2 3/8" 4.
3. Describe Pr	roposed or Compl RU. TOOH w/pump H w/bit. Circ &	Altering Casing _X_ Other - Tubing r .eted Operations a cods. ND WH. NU BO a CO to PBTD @ 6099'.	Convers epair P. TOOH w/2 TOOH w/bit.	3/8"	tbg. SD for weekenw/190 jts 2 3/8" 4.
3. Describe Pr	roposed or Compl RU. TOOH w/pump H w/bit. Circ &	Altering Casing _X_ Other - Tubing r .eted Operations a cods. ND WH. NU BO a CO to PBTD @ 6099'.	Convers epair P. TOOH w/2 TOOH w/bit.	3/8"	tbg. SD for weekenw/190 jts 2 3/8" 4.
3. Describe Pr	roposed or Compl RU. TOOH w/pump H w/bit. Circ &	Altering Casing _X_ Other - Tubing r .eted Operations a cods. ND WH. NU BO a CO to PBTD @ 6099'.	Convers epair P. TOOH w/2 TOOH w/bit.	3/8"	tbg. SD for weekenw/190 jts 2 3/8" 4. sed.
3. Describe Pr	roposed or Compl RU. TOOH w/pump H w/bit. Circ &	Altering Casing _X_ Other - Tubing r .eted Operations a cods. ND WH. NU BO a CO to PBTD @ 6099'.	Convers epair P. TOOH w/2 TOOH w/bit.	3/8"	tbg. SD for weekenw/190 jts 2 3/8" 4. sed.
3. Describe Pr	roposed or Compl RU. TOOH w/pump H w/bit. Circ &	Altering Casing _X_ Other - Tubing r .eted Operations a cods. ND WH. NU BO a CO to PBTD @ 6099'.	Convers epair P. TOOH w/2 TOOH w/bit.	3/8"	tbg. SD for weekenw/190 jts 2 3/8" 4. sed.
3. Describe Pr 6-30-00 MI 7-5-00 TI	roposed or Compl TRU. TOOH w/pump TH w/bit. Circ & J-55 tbg, set	Altering Casing _X_ Other - Tubing r .eted Operations a cods. ND WH. NU BO a CO to PBTD @ 6099'.	Convers epair P. TOOH w/2 TOOH w/bit. H. RD. Rig	3/8"	tbg. SD for weekenw/190 jts 2 3/8" 4.
3. Describe Pr 6-30-00 MI 7-5-00 TI	roposed or Compl TRU. TOOH w/pump TH w/bit. Circ & J-55 tbg, set	Altering Casing _X_ Other - Tubing relected Operations a & rods. ND WH. NU BO & CO to PBTD @ 6099'. @ 5997'. ND BOP. NU W	Convers epair P. TOOH w/2 TOOH w/bit. H. RD. Rig	3/8" TIH relea	tbg. SD for weeken. w/190 jts 2 3/8" 4. sed. JUL 2000 RECEIVED RECEIVED OLDON. DW
6-30-00 MI 7-5-00 TI	roposed or Complete. TOOH w/pump. TH w/bit. Circ & J-55 tbg, set ertify that the	Altering Casing _X_ Other - Tubing r eted Operations a rods. ND WH. NU BO c CO to PBTD @ 6099'. @ 5997'. ND BOP. NU W foregoing is true and Title Regulato	Convers epair P. TOOH w/2 TOOH w/bit. H. RD. Rig	3/8" TIH relea	tbg. SD for weeken. w/190 jts 2 3/8" 4. sed. JUL 2000 RECEIVED RECEIVE RECEI
3. Describe Pr 6-30-00 MI 7-5-00 TI	roposed or Complete. TOOH w/pump. TH w/bit. Circ & J-55 tbg, set ertify that the	Altering Casing _X_ Other - Tubing r eted Operations a rods. ND WH. NU BO c CO to PBTD @ 6099'. @ 5997'. ND BOP. NU W foregoing is true and Title Regulato	Convers epair P. TOOH w/2 TOOH w/bit. H. RD. Rig	3/8" TIH relea	tbg. SD for weeken w/190 jts 2 3/8" 4. sed. Sed. JUL 2000 DIST. 3