

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.<br>30-045-25214  |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name<br><br>John A. Brimhall  |
| 8. Well No.<br>#1   |
| 9. Pool name or Wildcat<br>Meadows Gallup   |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

|  |
|--|
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER   |
| 2. Name of Operator<br>JEROME P. McHUGH  |
| 3. Address of Operator<br>P O BOX 809, Farmington, N.M. 87499  |
| 4. Well Location<br>Unit Letter A : 860 Feet From The North Line and 380 Feet From The East Line<br>Section 10 Township 29N Range 15W NMPM San Juan County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br>5130'  |

|   |   |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data |   |
| NOTICE OF INTENTION TO:   | SUBSEQUENT REPORT OF:                               |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                                | REMEDIAL WORK <input type="checkbox"/>              |
| TEMPORARILY ABANDON <input type="checkbox"/>                                  | ALTERING CASING <input type="checkbox"/>            |
| PULL OR ALTER CASING <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>    |
| OTHER: <input type="checkbox"/>   | PLUG AND ABANDONMENT <input type="checkbox"/>       |
|   | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
|   | OTHER: <input type="checkbox"/>                     |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug and abandon as follows:

1. Spot 40 sx plug at 4427' - 3900' across perfs.
2. Spot 15 sx plug at 3114' - 2914' across DV tool.
3. Spot 15 sx plug at 1658' - 1458' across top Cliffhouse.

4. Perforate at 222'. Pump 80 sx of cement down 4-1/2" casing and up 8-5/8" casing. Volume should circulate with some excess. All calculation of cement volume based on neat cement at 1.18 cu.ft. per sx.

5. Cut off casing. Erect marker. Restore surface as directed by land owner.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Murphy Brasuel TITLE Field Supt. DATE 6/10/93  
TYPE OR PRINT NAME Murphy Brasuel TELEPHONE NO. 505 326-7793

(This space for State Use)

APPROVED BY Original Signed by CHARLES GRULSON TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUN 18 1993  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
JUN 15 1993  
OIL CON. DIV  
DIST. 3