# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells					
	5.	Lease Num			
GAS	6.	If Indian	n, All. or ne		
	7.	Unit Agre	eement Name		
Name of Operator MERIDIAN ©IL	8.	Well Name	e & Number		
3. Address & Phone No. of Operator		Cain #15h			
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. <b>API Well No</b> . 30-045-25328				
1. Location of Well, Footage, Sec., T, R, M	10.	Field and			
1730'FSL, 1520'FEL, Sec.31, T-29-N, R-9-W, NMPM	11.	Blanco MV/Basin DK County and State			
		San Juan	Co, NM		
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPO	RT, OTHER	DATA	<del></del>		
Type of Submission Type of Action					
X Notice of Intent Abandonment X Charles Recompletion New	ange of Pla . Construct				
Subsequent Report Plugging Back Nor	n-Routine	Fracturing	ſ		
Casing Repair Wat	er Shut o	ff			
Final Abandonment Altering Casing Cor X Other - Fish Mesaverde		5 Injectio	)11		
	cubing				
13. Describe Proposed or Completed Operations					
13. Describe Proposed or Completed Operations  It is intended to fish the Mesaverde tubing in the substantial procedure and wellbore diagram. It is	oject well	ided also	to commingl		
13. Describe Proposed or Completed Operations  It is intended to fish the Mesaverde tubing in the subattached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicati	oject well	ided also	to commingl		
13. Describe Proposed or Completed Operations  It is intended to fish the Mesaverde tubing in the substantial procedure and wellbore diagram. It is	oject well	ided also	to commingl		
13. Describe Proposed or Completed Operations  It is intended to fish the Mesaverde tubing in the subattached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicati	oject well	ided also	to commingl		
13. Describe Proposed or Completed Operations  It is intended to fish the Mesaverde tubing in the subattached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicati	oject well	ided also	to commingl		
13. Describe Proposed or Completed Operations  It is intended to fish the Mesaverde tubing in the subattached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicati	oject well	ided also	to commingl		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicational Conservation Division to commingle.	oject well	ided also	to commingl		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicational Conservation Division to commingle.	oject well now inter on has bee	ided also	to comming! the New Me		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicational Conservation Division to commingle.	oject well now inter on has bee	ided also	to comming! the New Me		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicational Conservation Division to commingle.	oject well now inter on has bee	ided also	to comming! the New Me		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicati Oil Conservation Division to commingle.  SEE ATTACHED CONSTITUTE OF APPR	oject well now inter on has bee	ided also	to comming! the New Me		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicational Conservation Division to commingle.  SEE ATTACHED TO SEE ATTACHED TO SOF APPR	oject well now inter on has bee	ided also	to comming! the New Me		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicati Oil Conservation Division to commingle.  SEE ATTACHED CONSTITUTE OF APPR	oject well now inter on has bee	ided also in made to	to comming! the New Me		
It is intended to fish the Mesaverde tubing in the substance of the Mesaverde and Wellbore diagram. It is the Mesaverde and Dakota formations. Applicational Conservation Division to commingle.  SEE ATTACHED CONSTITUTE OF APPROVALED CONSTITUTE OF APPROVAL (ROS3) Title Regulatory Additional Space for Federal or State Office use)	oject well now inter on has bee	ided also in made to	to comming! the New Me		
It is intended to fish the Mesaverde tubing in the substantial attached procedure and wellbore diagram. It is the Mesaverde and Dakota formations. Applicational Conservation Division to commingle.  SEE ATTACHED CONMITTONS OF APPROXIMATIONS OF APP	oject well now inter on has bee	r_Date 1/	to comming! the New Me		

OISTRICT MANAGER

# **PERTINENT DATA SHEET**

WELLNAME:	Cain #15M				DP NUMBER: PROP. NUMBER:		7758 0020291	775 <b>7</b> 00 <b>20291</b>	
WELL TYPE:	Blanco Mesave	erde/Basın Dako	ta		ELEVATION:	GL: KB:	5783' 579 <b>5</b> '		<u> </u>
LOCATION:	SE Sec. 31, T2	1520' FEL 29N, R9W nty, New Mexico			INITIAL POTENTIAL	L: AOF		MCF/D (MV)	
		, , , , , , , , , , , , , , , , , ,				Sept., 1991 March, 1992	362 372	PSIG (MV) PSIG (DK)	
OWNERSHIP:	GWI: IRN: SWB TBLE SURN TBLE	MV/DK 25.000000% 20.500000% 75.000000% 61.500000%			DRILLING:	C	SPUD DATE: OMPLETED: TAL DEPTH: PBTD: COTD:		03-11-82 04-17-82 6725' 6680'
CASING RECORD:									
HOLE SIZE	SIZE	WEIGHT	<u>GRADE</u>	DEPTH	EQUIP.		CEMENT	-	TOC
12-1/4"	8-5/8*	24.0#	K-55	2 <b>42</b> '	-	189 0	ಸ್ (160 sx)		surface
7-7 <b>/8*</b>	5-1/2*	15.5#	K-55	6724'	3rd stg, DV @ 2 2nd stg, DV @ 4 Float Collar @ 6	<b>1819</b> ' 1102	of (550 sx) of (750 sx) of (395 sx)		300' (TS) 2412' (759 4245' (759
Tubing (MV) Tubing (DK)	1-1/2" 1-1/2"	2.76# 2.3#	J-55 J-55	65' 66 <b>35</b> '					
(DK) Ran 1 jt 1-1/2	?", Seating Nipple				3#, J-55, tbg set at 65'	6635', Model "F	R" Production	packer @ 467	<b>7'</b> .
FORMATION TOPS:	Nacimiento				Chacra				
	Ojo Alamo		825'		Mesaverde		3025' 36 <b>23</b> '		
	Kirtland				Gallup		5532		
	Fruitland Pictured Cliffs		1790' 2062'		Greenhom Graneros		6311' 6375'		
	i icares cims		2002		Dakota		6497		
LOGGING:	IEL, CDL, CBL	, Temp Survey						,	·
PERFORATIONS		43', 6548', 6553' 688', 6690', 6692			', 6605', 6607', 6617', 6 des.	643', 6651'			
		394', 439 <mark>9', 44</mark> 04			', 4157', 4162', 4191', 4 9', 4424', 4436', 4443', 4				
STIMULATION:	(DK) Frac w/12	8,341 gal. of 30	<b>#</b> gel wtr.	and 57,97	5# of 20/40 sand.	· <del></del> ·			
	(MV) Frac w/22	21,812 gal. fresh	wtr. and	168,000#	20/40 sand.				
WORKOVER HISTORY:	May/June 1995	Circ well w/N TIH w/5-1/2* OK. Reset pk csg & tbg to s J-55 tbg & Me tbg. Changed	2. Blow w csg scrap or @ 4607 surface. P odel "R" p over broke	eil & CO. er. TiH w/i . Load ho T to 755#/ kr. landed off. Tbg d	fill. TOOH. TIH w/tbg kt TOOH w/MV tbg. Relea RBP & pkr. Set RBP @ le w/wtr. PT to 790#/10 10 min. OK. TIH, releas DK tbg @ 6635'. Set pl tropped to top of pkr @ WH. RD. Rig released.	se pkr, TOOH: 6472', set pkr: min, OK. Rese se RBP, SD for kr @ 4677', SD 4677', TOOH.	w//182 jts 1-1/ @ 6423'. PT F t pkr @ 3924' wknd. TIH w// ON, TIH w/13	'2" tbg & 5-1/2" RBP to 1100#/ . Load hole bei 215 jts 1-1/2", : 2 jts 1-1/2", 2.:	' pkr. 10 min, tween 2.3#, 3#, J-55
PRODUCTION HISTORY: Curnulative as of Oct. 95: Current Rate:	<u>Gas</u> 747.6 MMcf 100.4 Mcfd	<u>Oil</u> 15.4 MBo 1.84 Bopd	(DK) (DK)	<del></del>	DATE OF LAST PROD ೦ಡ.,	DUCTION: 1995	<u>Gas</u> 100.4 Mcf/D	Oil 1.84 bbl/D	(DK)
PRODUCTION HISTORY: Cumulative as of Oct. 95: Current Rate:	<u>Gas</u> 345.5 MMcf 0 Mcfd	<u>Qil</u> 12. <b>2 M</b> Bo 0 Bopd	(MV) (MV)		DATE OF LAST PROD May,	OUCTION: 1995	<u>Gas</u> 38.2 Mc/D	<u>Oil</u> 4.0 bbl/D	(MV)

## Cain #15M Blanco Mesaverde/Basin Dakota Dual SE Section 31, T-29-N, R-9-W Fishing and Commingle Procedure

- 1. Comply with all NMOCD, BLM and Meridian safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig.
- MOL and RU. Blow well down. NU 7-1/16" 3000 psi (6" 900 series) BOP with flow tee and stripping head. Test and record operation of BOP rams. Kill well with 1% KCL water only if necessary.
- 3. TOH with 2 joints of 1-1/2", 2.3#, J-55 Mesaverde tubing (Approximately 65'); visually inspect tubing and replace bad joints as necessary. PU and RIH with freepoint tool in the Dakota tubing. Locate freepoint, and chemically cut Dakota tubing 10' above freepoint (Model R retrievable packer set at 4677'). POH with wireline. TOH with Dakota tubing (1-1/2", 2.3#, J-55). Visually inspect tubing.
- 4. PU 2-3/8" workstring. TIH with overshot/grapple and fishing assembly, and attempt to catch 1-1/2" IJ tubing. TOH with fish. Fish DK and MV tubing as necessary.
- 5. After recovering fish, TIH with overshot and release Model "R" production packer (Release Model "R" packer by lifting up on tubing the length of the packer. Then lower the tubing slightly, the J-pin engages the J-slot assuring complete release and preventing accidental resetting) and TOH with packer and remaining 1-1/2" Dakota tubing.
- 6. Clean out to PBTD at 6680' with gas or air. Blow well clean and obtain gauges, and POOH.
- 7. TIH with 1-1/2" tubing with seating nipple and pump-out plug one joint off bottom. Land 1-1/2" tubing near bottom perfs at 6680'.
- 8. ND BOP and NU wellhead. Pump off pump-out plug and record final gauge. Return well to production as a commingled well.

Recommended:	KU Tanjero/
	V
Approved:	


Dasta KALQ

## Cain #15M

#### **CURRENT**

#### Blanco Mesaverde/Basin Dakota Dual

## SE Section 31, T-29-N, R-9-W, San Juan County, NM



## Cain #15M

### Proposed

#### Blanco Mesaverde/Basin Dakota Dual

SE Section 31, T-29-N, R-9-W, San Juan County, NM

