

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NM-E-10405
7. Unit Agreement Name
8. Farm or Lease Name State N
9. Well No. 1M
10. Field and Pool, or Wildcat Basin Dakota/Blanco M
12. County San Juan

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL OTHER-
2. Name of Operator Tenneco Oil Company
3. Address of Operator Box 3249, Englewood, CO 80155
4. Location of Well UNIT LETTER <u>D</u> <u>1230</u> FEET FROM THE <u>North</u> LINE AND <u>635</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>29N</u> RANGE <u>9W</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 5779' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/3/82: MIRUSU, Kill Well. NDWH, NUBOP. PU tbq & CO 25' of fill w/foam. Kill tbq, POOH. RIH w/model D pkr w/expendable plug. Set pkr @ 4570'. Dmp 2 sx sd on pkr. Load hole. PT csg to 3,000 psi. RIH w/4" csg gun. Perf w/1 JSPF 4288-95', 4398-4406' (15', 15 holes). Well blew in @ surface just after pulling bun thru lubricator. WL sheared dropping gun & 120' of WL in hole. Well blowing slightly out of csg. RIH w/bmpr sub, jars, string float & 2-pronged spear. Tagged fish, work 2-pronged spear. POOH, rec'd all WL.

11/4/82: RIH w/bmpr sub, jar & overshot. Set dn on fish. PU. Set jar off 3 times. Fish came free. Dakota gas to surface immediately. Wait for well to blow dn. Loks like expendable plugs were knocked out of model D when gun was dropped. Kill well. POOH w/tbg & overshot. Rec'd perf'g. gun. All fish rec'd. No marks on btm of perf'g gun.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ronnie Wilson</u>	TITLE <u>Production Analyst</u>	DATE <u>November 10, 1982</u>
APPROVED BY	TITLE	DATE <u>NOV 12 1982</u>

Original Signed

SUPERVISOR DISTRICT #

CONDITIONS OF APPROVAL, IF ANY: