ENERGY AND MINERALS DEPARTMENT			
NO. OF LOPIES ACCEIVED		ATION DIVISION	
DISTRIBUTION	P. O. BOX 2088  SANTA FE, NEW MEXICO 87501		Form C-103
SANTA FE'			Revised 10-1-
FILE	·		Sa. Indicate Type of Lease
U.S.G.S.		•	State Foe V
LAND OFFICE			5. State Oil 6 Gas Lease No.
OPERATOR		•	3. State Off & dos Least No.
SUNDRY  (DO NOT USE THIS FORM FOR PROPOS  USE "APPLICATION	NOTICES AND REPORTS OF	DIECELV.E	
OIL GAS WELL	OTHER-	AUG 1 71984	7. Unit Agreement Name
Name of Operator		011 0011 011/	8. Farm or Lease Name
Lobo Production	<del></del>	OIL CON. DIV.	11,1100 1101111
Address of Operator		DIST. 3	9. Well No.
PO Box 2364 Farm	ington, NM 87499		
Location of Well  UNIT LETTER 0 800	South	1885	10. Field and Pool, or Wildcan Cha Cha Gallup
THE/Eeat LINE, SECTION_	7 TOWNSHIP 29N	TANGE 14W	- NMPM. ([]]]]]]]]
	15, Elevation (Show whether	r DF, RT, GR, etc.)	12, County
	5205' Gr.		San Juan
Check Ap	propriate Box To Indicate	Nature of Notice, Report	or Other Data
NOTICE OF INT	• •	-	DUENT REPORT OF:
REFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
ILL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
THE OR ALTER CASING		OTHER	
OTHER			
	(6)	1	all dine estimated data of starting any propose
<ul> <li>Describe Proposed or Completed Opera work) SEE RULE 1103.</li> </ul>	tions (Clearly state all pertinent de	tails, and give perlinent dates, in	cluding estimated date of starting any propose
		4	
	•		
(Continued) Perfora Shut do	ted sub at 2630' and sown.	seating nipple at 262	9' KB. Landed well.
8-7-84 RIH w/rods an	d layed same down. Po Rigged down moved of	umped out plug from s ff location. Opened	eating nipple with water well to production
Init through	casing and and flower		well over to
production fo			
	_		
•			

Original Signed by FRANK T. CHAVEL

SUPERVISOR DISTRICT # 3

AUG 17 1984