4.		State of New Mexico			,	Form C 103		
	Submit 3 Copies to Appropriate District Office	Energy, Minerals and Natural Resources Department			Form C-103 Revised 1-1-89			
	OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088							
					WELL API NO	WELL API NO.		
	DISTRICT II Santa Fe, New Mexico 87504-2088 DISTRICT III				7. Indicate Typ	300452561700 ne of Lease		
					L. Maleute 131	STATE FEE X		
	TOUU Rio Brazos Rd., Aztec, NM 87410				6. State Oil &	Gas Lease No.		
	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease Name or Unit Agreement Name		
					7. Lease Name			
	(FORM C-101) FOR SUCH PROPOSALS.)					Candelaria A		
	I. Type of Well: OIL GAS WELL OTHER							
	WELL WEL 2. Name of Operator				8. Well No.	8. Well No.		
		CO PRODUCTION COMPANYY Gail M. Jefferson, Rm 1942			#1			
	3. Address of Operator P.O. Box 800 Denver	Colorado	80201	(303) 830-6157	9. Pool name o	ne or Wildcat Armenta Gallup		
4	4. Well Location Unit Letter C :	575 Feet From The	e North	Line and 1	660 Feet Fr	om The West	Line	
	Section 27	Township	29N R	ange 10W	NMPM	San Juan	County	
				er DF, RKB, RT, GR, etc.)			County	
L	U. Check	Appropriate Poy	to Indicate N	Vature of Notice D	lanart or Otl	nor Doto		
	Check Appropriate Box to indicate relative of Notice, Re				Sport, or Other Data BSEQUENT REPORT OF:			
D	۲	 1	ANDON X				Γ-	
	ERFORM REMEDIAL WORK	PLUG AND AB		REMEDIAL WORK		ALTERING CASING	L.	
T	EMPORARILY ABANDON	ARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS			OPNS.	PLUG AND ABANDO	NMENT	
М	ULL OR ALTER CASING	_]		CASING TEST AND C	EMENT JOB			
0	THER: Plug And	Abandon		OTHER:			[
1	Describe Proposed or Complete work) SEE RULE 1103.	d Operations (Clearly sta	te all pertinent deta	l ils, and give pertinent dates,	including estimate	d date of starting any prop	osed	
	Amoco Production Compa	ny requests permiss	ion to plug and	abandon the above ref	erenced well pe	er the attached proce	dures.	
	If you have any technical of listed below.	questions please cor	itact Mike Kuta	s at (303) 830-5159 o	r Gail Jeffersor	at the telephone nur	mber	
					[D]	ECENVIN	garange Silyan K	
					in("			
					u u	MAR 2 9 1995		
				35,	001	LCOM ENTER	. ,	
						LCON. DIV Dist. 2	/5	
	I hereby certify that the informatio	n above is true and comp						
	SIGNATURE Xau	1. Affersor	\smile	Business A	Assistant	DATE 03-28-1	995	
7	TYPE OR PRINT NAME G	ail M. Jefferson, Rm	1942			TELEPHONE NO. (303)	830-6157	
	(This space for State Use)	01-					·	
	Ornmas	Kolumo	n	DEPUTY OIL & GAS II	NSPECTOR DIST	. 43 MAD	9 0 40	
	APPROVED BY	1 ()		TITLE	THE PRINCIPLE	DATE WAT	c 7 14	
	APPROVED BY JOHNNY CONDITIONS OF APPROVAL, IF ANY:	* Notity in	time to	withess				

Candelaria A #1
Orig. Comp. 4/29/83
TD = 5902', PBTD = 5850'
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water.
- POOH with 2 3/8" tbg. NDWH. NUBOP. RIH with tbg and cement retainer. Set retainer at 5275'. Test casing integrity to 500#. Squeeze perfs at 5338' to 5650' with 192 cuft of cement. Pull out of retainer and spot cement plug to 3350' with 264 cuft cement.
- 4. Pull hp hole and spot cement plug across the following formations:

Chacra at 2500'
Pictured Cliffs at 1835'
Fruitland Coal at 1585' to surface
(estimate 245 cuft cement)

- NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

