

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3004525618
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Sanchez Gas Com C
2. Name of Operator Amoco Production Company Pat Archuleta, Room 1205C	8. Well No. #1
3. Address of Operator P.O. Box 800 Denver, CO 80201 (303) 830-5217	9. Pool name or Wildcat Blanco Mesaverde
4. Well Location Unit Letter A : 750 Feet From The North Line and 660 Feet From The East Line Section 28 Township 29N Range 10W NMPM San Juan County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company requests permission to plug and abandon this well per the attached procedures.

RECEIVED
NOV - 4 1996
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Pat Archuleta TITLE Clerk DATE 10-31-96
TYPE OR PRINT NAME Pat Archuleta TELEPHONE NO. (303) 830-5217

(This space for State Use)

APPROVED BY Johnny Robinson DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE NOV 0 4 1996
CONDITIONS OF APPROVAL, IF ANY:

NOTIFY AZTEC OCD
IN TIME TO WITNESS

PJA

Sanchez Gas Com C #1
Orig. Comp. 12/84
TD = 5852' PBTD = 5800'
Page 2 of 2

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
3. POOH with 2 3/8" tbg and production packer. RIH with tbg and CIBP. Set CIBP at 3395'. Test csg integrity to 500#. Spot 100' cement plug on top of CIBP. (20 cuft cement). Pull up hole and spot 100' cement plug across the Chacra at 2380' to 2480'. (20 cuft cement), Pictured Cliff at 1733' to 1833'. (20 cuft cement), Fruitland at 1210' to 1310'. (20 cuft cement), Ojo Alamo at 525' to 625'. (20 cuft cement), and 385' to surface. (58 cuft cement).
4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
5. Contact FMC and ship surface equipment to yard or other location per instructions.
6. Turn over to John Schwartz for reclamation.
7. Rehabilitate location according to BLM or State requirements.