

Submit 3 Copies  
to appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**

P.O. Box 2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

3004525672

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Pollock Corn D

8. Well No.

1

9. Pool name or Wildcat

Armenta Gallup

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

Amoco Production Company

Attention:

Lois Raeburn

3. Address of Operator

P.O. Box 800 Denver Colorado 80201

4. Well Location

Unit Letter M : 910 Feet From The South Line and 500 Feet From The West Line

Section 27 Township 29N Range 10W NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

5549' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company request permission to Plug and Abandon the above named well.

See Attached Procedure.

RECEIVED  
APR 25 1994

OIL CON. DIV.  
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Lois Raeburn*

TITLE

Business Asst.

DATE

04-20-1994

TYPE OR PRINT NAME

Lois Raeburn

TELEPHONE NO. (303) 830-5294

(This space for State Use)

APPROVED BY

Original Signed by CHARLES GHOLSON

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

APR 25 1994

CONDITIONS OF APPROVAL, IF ANY:

11

Pollack Com D # 1  
PXA Procedures

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow down well. Kill if necessary with fresh water.
3. POOH with 2 3/8" tbg. RIH with tbg and cementretainer, set retainer at 5275'. Test casing integrity to 500#. Squeeze perfs at 5336-5646 with 210.5 cuft cement. Pull out of retainer and spot cement plug to 5225' with 10.32 cuft cement.
4. Run short string CBL to determine TOC.
5. Depending on TOC make sure the following formations are covered 100' inside and outside casing:

Mesa Verde @ 3400'  
Pictured Cliffs @ 1820'  
Fruitland @ 1477  
Ojo Alamo @ 575' to surface
6. NDBOPE. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
7. Turn over to John Schwartz for reclamation.
8. Rehabilitate location according to BLM or State requirements.

POLLOCK COM D #1  
LOCATION, 27M-29N-10W  
SINGLE GP  
ORIGINAL COMPLETION 7/83  
LAST FILE 1/94 BY CSW  
ELEVATION KB 5549

QJ AT 575

KL AT 1295

PC AT 1820

MV AT 3400

GP AT 5332

GP-1JSP2F PERF 5336-5450

GP-1JSPF PERF 5474-5530

5564-5646

PBTD AT 5790 FT.

FILENAME:  
04525672

TOTAL DEPTH 5927 FT.

BOT OF 11.75 IN OD CSA 308  
42 LB/FT. H-5 CASING  
CTR TO SURFACE

DV TOOL @ 300

BOT OF 2.375 IN OD TBG AT 5716

BOT OF 5.5 IN OD CSA 5926  
15.5 LB/FT. K-55 CASING