2. Tuned tubing and veran open enterty	•
3. Spotted 19 sk cement plug (total cement slurry 22.42 cu.ft.) 43	339' - 4089'.
4. Spotted 8 sk cement plug (total cement slurry 9.44 cu.ft.) 105'	to surface.
5. Installed dry hole marker.	
6. Removed all equipment and restored location.	ECEIVER
*Note: Cementing done 3-26-86. Location restored 4-10-86.	APR 161986
OI	L CON. DIV
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Jim L. Jacobs	9ATE 4-14-86
Original Signed by CHARLES GHOLSON DEPUTY GIL & GAS INSPECTOR, DIST. #3	APR 1 6 1986
CONDITIONS OF APPROVAL, IF ANY:	